

Oakland Fire Department, Fire Prevention Bureau 250 Frank H. Ogawa Plaza, Ste. 3341 Oakland, CA 94612-2032



Report of Fire Inspection

Date

7/11/2012

Facility / Site Location

ALHAKIM ABDUL J

7633 SUNKIST DR

7633 SUNKIST DR

OAKLAND

CA 94605

OAKLAND CA

94605-3024

Pursuant to OMC Sec. 15.12, a Vegetation inspection was conducted on 7/11/2012 at the site location which found the facility to be **Non-Compliant** with City of Oakland fire regulations. In accordance with CFC 104.5 you are hereby ordered to immediately correct all upon receipt of this notice. Failure to comply with this lawful order may result in a citation to appear in Municipal Court, plus additional fees and civil penalties.

Deficiency

Corrective Action

Deficiency Status

Location

CFC 4907.1.1

Maintain a 30-foot fuel reduction zone around all buildings/structures; more may be required as designated by the fire marshal.

Unsatisfactory

An inspection has been scheduled to determine if you have complied with this order on August 11, 2012 12:00 am. The inspection/permit fees will be invoiced at a later date. If any violations are found during the reinspection, additional inspection fees and penalties will be charged.

Should you have any questions, please call (510) 238-3851

Sincerely,

Foley, Christopher, Lieutenant Oakland Fire Department

Inspection Ref # 2011-65436



Oakland Fire Department, Fire Prevention Bureau 250 Frank H. Ogawa Plaza, Ste. 3341 Oakland, CA 94612-2032



Report of Fire Inspection

Date

8/28/2012

Facility / Site Location

ALHAKIM ABDUL J

7633 SUNKIST DR

7633 SUNKIST DR

OAKLAND

CA 94605

OAKLAND CA

94605-3024

Pursuant to OMC Sec. 15.12, a Vegetation inspection was conducted on 8/28/2012 at the site location which found the facility to be **Non-Compliant** with City of Oakland fire regulations. In accordance with CFC 104.5 you are hereby ordered to immediately correct all upon receipt of this notice. Failure to comply with this lawful order may result in a citation to appear in Municipal Court, plus additional fees and civil penalties.

Deficiency

Corrective Action

Deficiency Status

Location

CFC 4907.1.1

Maintain a 30-foot fuel reduction zone around all buildings/structures; more may be required as designated by the fire marshal.

Satisfactory?

An inspection has been scheduled to determine if you have complied with this order on . The inspection/permit fees will be invoiced at a later date. If any violations are found during the reinspection, additional inspection fees and penalties will be charged.

Should you have any questions, please call (510) 238-3851

Sincerely,

Sanders, Anthony, Administrator Oakland Fire Department

Inspection Ref # 2012-10205