



#### Report of Fire Inspection

Date

8/7/2015

The Swig Company, #206

Facility / Site Location

300 LAKESIDE DR #210, 1400,1500

300 Lakeside Drive, Suite 206

OAKLAND

CA 94612

Oakland, CA

94612

Pursuant to OMC Sec. 15.12, a Occupancy inspection was conducted on 8/7/2015 at the site location which found the facility to be **Non-Compliant** with City of Oakland fire regulations. In accordance with CFC 104.5 you are hereby ordered to immediately correct all upon receipt of this notice. Failure to comply with this lawful order may result in a citation to appear in Municipal Court, plus additional fees and civil penalties.

Deficiency

Corrective Action

**Deficiency Status** 

Location

CFC 703.2.2 a

Repair/Replace self-closing -latching mechanisms

Satisfactory

Hallway Banquet

[B] 1008.1

[B] 1008.1.9.3 Locks and latches.

Locks and latches shall be permitted to prevent operation of doors where any of the following exists:

Unsatisfactory

2.2. A readily visible durable sign is posted on the egress side on or adjacent to the door stating: THIS DOOR TO REMAIN UNLOCKED WHEN BUILDING IS OCCUPIED. The sign shall be in letters 1-inch (25 mm) high on a contrasting background; and

[B] 607.2

[B] 607.2 Emergency signs.

An approved pictorial sign of a standardized design shall be posted adjacent to each elevator call station on all floors instructing occupants to use the exit stairways and not to use the elevators in case of fire. The sign shall read: IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS

Informational Only

[B] 1011.5

[B] 1011.5 Internally illuminated exit signs.

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Chapter 27 of the California Building Code. Exit signs shall be illuminated at all times.

Unsatisfactory

OMC 5.04.040

Obtain/Post valid City of Oakland Business Tax Certificate.

Unsatisfactory

#### **DIVISION II ADMINIS**

[A] 105.6.34 Places of assembly.
An operational permit is required to operate a place of assembly.
Maximum Occupancy
Restaurant/Dining-268
Garden Room-284
Garden Room Terrace-505
Total = 1057

Unsatisfactory

Informational Only

Inspection of Roof Garden Terrace & Restaurant

An inspection has been scheduled to determine if you have complied with this order on . The inspection/permit fees will be invoiced at a later date. If any violations are found during the reinspection, additional inspection fees and penalties will be charged.

Should you have any questions, please call (510) 238-3851 or send email to pglover@oaklandnet.com

Sincerely,

Glover, Pamela, Inspector Oakland Fire Department

Inspection Ref # 2015-38103





# **Inspection Work Order**

Business Name:

The Swig Company, #206

Reason:

Address:

300 LAKESIDE DR #210, 1400,1500

Scheduled:

2015-08-07 1:00PM

Job (Insp Ref#):

2015-38103

Assigned To:

Glover, Pamela

Comments:

Inspection of Roof Garden Terrace & Restaurant

Public Assembly 268-Dining (seating), Roof Garden Terrace -505 (seating)

Invoice #

2015-04873

Applicant:

Irma Flores

Invoice Amount

409.00

Applicant Ph#:

510-271-6188

Contractor:

Contractor Ph#:







### Report of Fire Inspection

Date

12/3/2011

Irma Flores/Kathy Pozos

SIC-LAKESIDE DRIVE LLC c/o The Swig Company/Kaiser Towe

300 Lakeside Dr., Suite 206

Oakland, CA

94612

Facility / Site Location

domey / One Location

300 LAKESIDE DR #210, 1400,1500

OAKLAND

CA 94612

Pursuant to OMC Sec. 15.12, a C.U.P.A. inspection was conducted on 12/3/2011 at the site location which found the facility to be **Non-Compliant** with City of Oakland fire regulations. In accordance with CFC 104.5 you are hereby ordered to immediately correct all upon receipt of this notice. Failure to comply with this lawful order may result in a citation to appear in Municipal Court, plus additional fees and civil penalties.

Deficiency

Corrective Action

Deficiency Status

Location

CFC 703.1 #2

Repair, restore or replaced damaged, altered, or breached all penetrations to fire-resistive rated construction.

Replace ALL missing ceiling tiles

Satisfactory

3rd Floor server room

An inspection has been scheduled to determine if you have complied with this order on . The inspection/permit fees will be invoiced at a later date. If any violations are found during the reinspection, additional inspection fees and penalties will be charged.

Should you have any questions, please call (510) 238-3851 or send email to cavila@oaklandnet.com

Sincerely,

Avila, Cesar, Inspector Oakland Fire Department

Inspection Ref # 2011-45986





# **Inspection Work Order**

Business Name:

SIC-LAKESIDE DRIVE LLC c/o The Swig Co

Reason:

Annual

Address

300 LAKESIDE DR #210, 1400,1500

Scheduled:

2011-12-03 9:00AM

Job (Insp Ref#):

2011-45986

Assigned To:

Avila, Cesar

Comments:

Invoice #

2012-00083

Applicant:


Invoice Amount

11,839.31

Applicant Ph#:

Contractor:

Contractor Ph#:



DIVISION II DIVISION II ADMINISTRATION	Permit Condition
APMINISTR ATIUS 6.34 Places of assembly. An operational permit is required to operate a place of assembly.	04/23/2015
CFC 703.1 CFC 703.1 #1 Doors self-closing and tight	Satisfactory
EFC 703.1 #1 latching	04/23/2015
Openings through fire-resistance-rated assemblies shall be protected by self- or automatic-closing doors of approved construction meeting the fire protection requirements for the assembly.	
1001.2 Minimum requirements.	Satisfactory
1001.2 Minimum requirements.  It shall be unlawful to alter a building or structure in a manner that will reduce the number of exits or the capacity of the means of egress to less than required by this code.	04/21/2015
605.5 Extension cords.	Satisfactory
605.5 Extension cords.  Extension cords and flexible cords shall not be a substitute for permanent wiring. Extension cords and flexible cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances.	04/21/2015
HMBP.1.2 Facility failed to submit the required	Satisfactory
H&SC 25505 Hazardous Material Business Plan Agency records do not contain the HMBP nor any record that is was received. Submit the Hazardous Materials Business Plan within 30 days of notification by the administering agency.	03/05/2015
Freight lobby	Satisfactory
	04/21/2015
	22,000
CFC 703.2.2 CFC 703.2.2 a Door closures in good Hallway Banquet  working order Repair/Replace self-crosing -latching mechanisms	Unsatisfactory
[B] 1008.1 [B] 1008.1 Doors.	Unsatisfactory
[B] 1008.1.9.3 Locks and latches. Locks and latches shall be permitted to prevent operation of doors where any of the following exists:	Contract of the state of the st
2.2. A readily visible durable sign is posted on the egress side on or adjacent to the door stating: THIS DOOR TO REMAIN UNLOCKED WHEN BUILDING IS OCCUPIED. The sign shall be in letters 1-inch (25 mm) high on a contrasting background; and	
[B] 607.2 [B] 607.2 Emergency signs.	Informational On
[B] 607.2 Emergency signs.  An approved pictorial sign of a standardized design shall be posted adjacent to each elevator call station on all floors instructing occupants to use the exit stairways and not to use the elevators in case of fire. The sign shall read: IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS	and it from the contract of
[B] 1011.5 [B] 1011.5 Internally illuminated exit signs.	Uneatiefactor
[B] 1011.5 Internally illuminated exit signs.  Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Chapter 27 of the California Building Code. Exit signs shall be illuminated at all times.	Unsatisfactory

Printed 9/24/2015

Page 5 of 6