Work Order ID #	749374			
Work Order Category	SEWERS			
Work Order Description	Sewers - Clean - Flush			
Work Order Address	2525 10TH AVENUE			
Submit To	LOZANO, ARMANDO A			
By LOZANO, ARMANDO A: 3/15/2016 6:40				
Flushed and removed very heavy debris for	cctv Garcia.			
	Ø-			
Priority	3 - Medium			
Supervisor	GUZMAN, MIGUEL			
Cityworks Project Name				
Initiated By	LOZANO, ARMANDO A			
Initiated Date	3/15/2016 6:38:59 PM			
Actual Start Date	3/15/2016 7:00:00 AM			
Actual Finish Date	3/15/2016 1:00:00 PM			
Police Beat	17Y			
Service Delivery District	3			
City Council District	CCD2			
Total Entities (GIS Assets) on Work Order	4			
Units Accomplished	1080			
Units Accomplished Description	Linear Feet			
Total Work Order Cost	\$922.08			
Total Of Work Order Labor Costs	\$809.28			
Total Of Work Order Material Costs	\$0.00			
Total Of Work Order Equipment Costs	\$112.80	14.7		

#### Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$454.80	LOZANO, ARMANDO A	6.00	3/15/2016 7:00:00 AM	3/15/2016 1:00:00 PM
\$354.48	MILLER, DONALD M	6.00	3/15/2016 7:00:00 AM	3/15/2016 1:00:00 PM

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$112.80	4291 - 2012 AQUATECH B10 COMBO FLUSHER	4291	6.00			\$112.80	Hourly

		327					1
N	n	а	Ľ	ы	۲ı	a	

Material Cost	Description	Material UID	Mat Unit	Units
			Cost	Required

#### **Entities**

Entity UID	Entity Type	
13341	SANITARYSEWERCOLLECTIONSYSTEM	
13342	SANITARYSEWERCOLLECTIONSYSTEM	
15515	SANITARYSEWERCOLLECTIONSYSTEM	
15514	SANITARYSEWERCOLLECTIONSYSTEM	

Custom Fields	
Custom Field Names	Custom Field Value
HOT SPOT	
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	3

Lauren ny any ann	- 1
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	_
(LAT) DYE SHOW IN OTHER	_
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	4 - Heavy
CLEANING OBSERVATION - DEBRIS  CLEANING OBSERVATION - GREASE	1 - Clear
CLEANING OBSERVATION - GREASE  CLEANING OBSERVATION - ROOTS	1 - Clear
CLEANING OBSERVATION - ROOTS  CLEANING OBSERVATION - OTHER	1 - Clear
	i - Gleai
CLEANING OBSERVATION - OTHER	

Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status
		Priority	Address	Initiated		800 800	

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of
							Call

Work Order ID #	748172			
Work Order Category	SEWERS			
Work Order Description	Sewers - Clean PM - Flush			
Work Order Address	BELLA VISTA AV & E 28TH ST			
Submit To	EVANS, CHARLIE			
By EVANS, CHARLIE: 3/11/2016 3:05:46 PM	Л			
	THAT ARE IN THIS WORK ORDER AND THE			
LINE ARE CLEAN AND FLOWING STRONG	G AND READY TO BE CCTV.			
Priority	3 - Medium			
Supervisor	GUZMAN, MIGUEL			
Cityworks Project Name	Sewers Unique Footage Cleaning			
Initiated By	SWITHENBANK, AL			
Initiated Date	3/11/2016 7:09:02 AM			
Actual Start Date	3/11/2016 12:00:43 PM			
Actual Finish Date	3/11/2016 3:00:54 PM			
Police Beat	17Y			
Service Delivery District	3			
City Council District	CCD2			
Total Entities (GIS Assets) on Work Order	8			
Units Accomplished	1900			
Units Accomplished Description	Linear Feet			
Total Work Order Cost	\$461.04			
Total Of Work Order Labor Costs	\$404.64			
Total Of Work Order Material Costs	\$0.00			
Total Of Work Order Equipment Costs	\$56.40			

Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$227.40	EVANS, CHARLIE	3.00	3/11/2016 12:00:00 AM	3/11/2016 12:00:00 AM
\$177.24	MONDY, DEANDRE	3.00	3/11/2016 12:00:00 AM	3/11/2016 12:00:00 AM

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$56.40	4291 - 2012 AQUATECH B10 COMBO FLUSHER	4291	3.00	3/11/2016 12:00:00 AM	3/11/2016 12:00:00 AM	\$56.40	Hourly

Material

Material				
Material Cost	Description	Material UID	Mat Unit	Units
			Cost	Required

Entities

Entity UID	Entity Type	
15515	SANITARYSEWERCOLLECTIONSYSTEM	
15514	SANITARYSEWERCOLLECTIONSYSTEM	
13342	SANITARYSEWERCOLLECTIONSYSTEM	K. Para and Property
15510	SANITARYSEWERCOLLECTIONSYSTEM	
15511	SANITARYSEWERCOLLECTIONSYSTEM	
13305	SANITARYSEWERCOLLECTIONSYSTEM	
13304	SANITARYSEWERCOLLECTIONSYSTEM	
13343	SANITARYSEWERCOLLECTIONSYSTEM	

Custom Field Names	Custom Field \ falue
HOT SPOT	Custom Field Value
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) BYE GROW IN OTHER SIZE ESII  (LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY (LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	4 - Heavy
CLEANING OBSERVATION - GREASE	4 - Heavy
CLEANING OBSERVATION - ROOTS	2 - Light
CLEANING OBSERVATION - OTHER	N/A
CLEANING OBSERVATION - OTHER	

Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status	
		Priority	Address	Initiated	W	9 <del>7</del> 0 A		

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of
							Call

SEWERS
Sewers - CCTV
1555 LAKESIDE DR
FORD, CHARLES

By FORD, CHARLES: 3/17/2016 7:25:22 AM

CCTV M/S FOR SPECIAL INSPECTION OF THE M/S WE WAS UNABLE TO COMPLETE THE INSPECTION DUE TO CAMERA UNDER WATER NEED TO FOLLOW THE HYDRO BACK TO COMPLETE LINE HAS A COUPLE OF SAGS ASSET#31496

By FORD, CHARLES: 3/17/2016 7:28:15 AM SLIP LINE

Priority	3 - Medium	
Supervisor	AMATE, DAVID J	
Cityworks Project Name		
Initiated By	FORD, CHARLES	
Initiated Date	3/16/2016 9:46:49 AM	
Actual Start Date	3/16/2016 1:00:27 PM	
Actual Finish Date	3/16/2016 3:00:01 PM	
Police Beat	17Y	
Service Delivery District	3	
City Council District	CCD2	
Total Entities (GIS Assets) on Work Order	2	
Units Accomplished	126	
Units Accomplished Description	Linear Feet	
Total Work Order Cost	\$292.66	
Total Of Work Order Labor Costs	\$269.76	
Total Of Work Order Material Costs	\$0.00	
Total Of Work Order Equipment Costs	\$22.90	

#### Labor

Labor				
Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$151.60	FORD, CHARLES	2.00	3/16/2016 1:00:00 PM	3/16/2016 3:00:00 PM
\$118.16	PHARR, STEPHAN L	2.00	3/16/2016 1:00:00 PM	3/16/2016 3:00:00 PM

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$22.90	4384 - SEWERS CCTV HI-CUBE	4384	2.00	3/16/2016 1:00:00 PM	3/16/2016 3:00:00 PM	\$22.90	Hourly

/laterial

Material					
Material Cost	Description	Material UID	Mat Unit Cost	Units Required	1

**Entities** 

Entity UID	Entity Type	
13341	SANITARYSEWERCOLLECTIONSYSTEM	
12154	SANITARYSEWERSTRUCTURES	

Custom Field Names	Custom Field Value
HOT SPOT	
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	

CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY PATS-OIL-GREASE  CAUSED BY DEBRIS	
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	N/A
CLEANING OBSERVATION - GREASE	N/A
CLEANING OBSERVATION - ROOTS	N/A
CLEANING OBSERVATION - OTHER	N/A
CLEANING OBSERVATION - OTHER	

Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status
A Company of the Comp		Priority	Address	Initiated			

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of
							Call

Work Order ID #	750993
Work Order Category	SEWERS
Work Order Description	Sewers - CCTV
Work Order Address	2609 10TH AVE
Submit To	GARCIA, CESAR A
By GARCIA, CESAR A: 3/22/2016 5:45:32 P	'M
THE CONDITION OF THIS M/S IS GOOD A	ND CLEAN.
Priority	3 - Medium
Supervisor	AMATE, DAVID J
Cityworks Project Name	
Initiated By	GARCIA, CESAR A
Initiated Date	3/22/2016 5:44:08 PM
Actual Start Date	3/17/2016 8:00:47 AM
Actual Finish Date	3/17/2016 11:00:56 AM
Police Beat	17X
Service Delivery District	3
City Council District	CCD2
Total Entities (GIS Assets) on Work Order	1
Units Accomplished	305
Units Accomplished Description	Linear Feet
Total Work Order Cost	\$464.34
Total Of Work Order Labor Costs	\$404.64
Total Of Work Order Material Costs	\$0.00
Total Of Work Order Equipment Costs	\$59.70

Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$177.24	FOSTER, LARRY	3.00	3/17/2016 12:00:00 AM	3/17/2016 12:00:00 AM
\$227.40	GARCIA, CESAR A	3.00	3/17/2016 12:00:00 AM	3/17/2016 12:00:00 AM

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$59.70	4184 - TRUCK 1T UTILITY BODY	4184	3.00	3/17/2016 12:00:00 AM	3/17/2016 12:00:00 AM	\$59.70	Hourly

Material

Material Cost	Description	65	Material UID	Mat Unit	Units
				Cost	Required

Entities

Littles	
Entity UID	Entity Type
13342	SANITARYSEWERCOLLECTIONSYSTEM

Custom Fielus	
Custom Field Names	Custom Field Value
HOT SPOT	
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	

CAUSED BY VANDALISM	I .
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	14.7
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	1 - Clear
CLEANING OBSERVATION - GREASE	1 - Clear
CLEANING OBSERVATION - ROOTS	1 - Clear
CLEANING OBSERVATION - OTHER	1 - Clear
CLEANING OBSERVATION - OTHER	

 Abboolated of the request								
Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status	
	522	Priority	Address	Initiated		1000 2000		

Work Order ID #	749210				
Work Order Category	SEWERS				
Work Order Description	Sewers - CCTV				
Work Order Address	2617 10TH AV				
Submit To	FORD, CHARLES				
By FORD, CHARLES: 3/17/2016 7:13:08 AN CCTV M/S FOR UNIQUE FOOTAGE INSPE LINES ARE GOOD					
Priority	3 - Medium				
Supervisor	AMATE, DAVID J				
Cityworks Project Name					
Initiated By	FORD, CHARLES				
Initiated Date	3/15/2016 1:02:56 PM				
Actual Start Date	3/16/2016 8:00:40 AM				
Actual Finish Date	3/16/2016 11:00:53 AM				
Police Beat	17Y				
Service Delivery District	3				
City Council District	CCD2				
Total Entities (GIS Assets) on Work Order	7				
Units Accomplished	1088.5				
Units Accomplished Description	Linear Feet				
Total Work Order Cost	\$438.99				
Total Of Work Order Labor Costs	\$404.64				
Total Of Work Order Material Costs	\$0.00				
Total Of Work Order Equipment Costs	\$34.35				

### Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$177.24	PHARR, STEPHAN L	3.00	3/17/2016 8:00:00 AM	3/17/2016 11:00:00 AM
\$227.40	FORD, CHARLES	3.00	3/17/2016 8:00:00 AM	3/17/2016 11:00:00 AM

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$34.35	4384 - SEWERS CCTV HI-CUBE	4384	3.00	3/17/2016 8:00:00 AM	3/17/2016 11:00:00 AM	\$34.35	Hourly

Material

11101001101					
Material Cost	Description	Material UID	Mat Unit	Units	
			Cost	Required	

# Entities

Entity UID	Entity Type	was an over a second fire
15515	SANITARYSEWERCOLLECTIONSYSTEM	
15514	SANITARYSEWERCOLLECTIONSYSTEM	
13342	SANITARYSEWERCOLLECTIONSYSTEM	0
28075	SANITARYSEWERSTRUCTURES	
28074	SANITARYSEWERSTRUCTURES	
13341	SANITARYSEWERCOLLECTIONSYSTEM	
12154	SANITARYSEWERSTRUCTURES	

Custom Field Names	Custom Field Value
HOT SPOT	

BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	N/A
CLEANING OBSERVATION - GREASE	N/A
CLEANING OBSERVATION - ROOTS	N/A
CLEANING OBSERVATION - OTHER	N/A
CLEANING OBSERVATION - OTHER	

Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status
		Priority	Address	Initiated			

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of
5.03047999997,603009497,40399			550500 D 1507 D				Call

Work Order ID #	748844
Work Order Category	SEWERS
Work Order Description	Sewers - CCTV
Work Order Address	2701 10TH AV
Submit To	GARCIA, CESAR A
	M OOD. WE NEED TO FLUSH M/S ASSET# 13342 BLE TO GO 80FT DUE TO HEAVY DEBRIS.
Priority	3 - Medium
Supervisor	AMATE, DAVID J
Cityworks Project Name	
Initiated By	GARCIA, CESAR A
Initiated Date	3/14/2016 12:46:36 PM
Actual Start Date	3/14/2016 10:00:49 AM
Actual Finish Date	3/14/2016 2:00:03 PM
Police Beat	17Y
Service Delivery District	3
City Council District	CCD2
Total Entities (GIS Assets) on Work Order	2
Units Accomplished	420
Units Accomplished Description	Linear Feet
Total Work Order Cost	\$619.12
Total Of Work Order Labor Costs	\$539.52
Total Of Work Order Material Costs	\$0.00
Total Of Work Order Equipment Costs	\$79.60

Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$236.32	FOSTER, LARRY	4.00	3/14/2016 12:00:00 AM	3/14/2016 12:00:00 AM
\$303.20	GARCIA, CESAR A	4.00	3/14/2016 12:00:00 AM	3/14/2016 12:00:00 AM

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$79.60	4184 - TRUCK 1T UTILITY BODY	4184	4.00	3/14/2016 12:00:00 AM	3/14/2016 12:00:00 AM	\$79.60	Hourly

Material

Material Cost	Description	Material UID	Mat Unit	Units	
			Cost	Required	

**Entities** 

Entity UID	Entity Type	
15515	SANITARYSEWERCOLLECTIONSYSTEM	
15514	SANITARYSEWERCOLLECTIONSYSTEM	

Custom Field Names	Custom Field Value
HOT SPOT	
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	
CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	

CAUSED BY COLLAPSE	I
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	-
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	3 - Moderate
CLEANING OBSERVATION - GREASE	1 - Clear
CLEANING OBSERVATION - ROOTS	1 - Clear
CLEANING OBSERVATION - OTHER	1 - Clear
CLEANING OBSERVATION - OTHER	

Associated 5	ervice Request						
Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status
	5000	Priority	Address	Initiated		80.00	

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of
							Call

Work Order 749805	
Work Order ID #	749805
Work Order Category	SEWERS
Work Order Description	Sewers - CCTV
Work Order Address	2516 10TH AVE
Submit To	GARCIA, CESAR A
By GARCIA, CESAR A: 3/17/2016 9:46:01 A THE CONDITION OF THIS M/S IS GOOD.	M
By GARCIA, CESAR A: 3/17/2016 9:47:53 A WE HAD THIS LINE FLUSHED TO CLEAR I	
Priority	3 - Medium
Supervisor	AMATE, DAVID J
Cityworks Project Name	
Initiated By	GARCIA, CESAR A
Initiated Date	3/17/2016 9:46:01 AM
Actual Start Date	3/15/2016 8:00:20 AM
Actual Finish Date	3/17/2016 11:00:29 AM
Police Beat	17Y
Service Delivery District	3
City Council District	CCD2
Total Entities (GIS Assets) on Work Order	1
Units Accomplished	430
Units Accomplished Description	Linear Feet
Total Work Order Cost	\$464.34
Total Of Work Order Labor Costs	\$404.64

Labor

Total Of Work Order Material Costs

Total Of Work Order Equipment Costs

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$177.24	FOSTER, LARRY	3.00	3/15/2016 12:00:00 AM	3/15/2016 12:00:00 AM
\$227.40	GARCIA, CESAR A	3.00	3/15/2016 12:00:00 AM	3/15/2016 12:00:00 AM

\$0.00

\$59.70

Equipment

Equipment Cost	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit Cost	Equipment Rate Type
\$59.70	4184 - TRUCK 1T UTILITY BODY	4184	3.00	3/15/2016 12:00:00 AM	3/15/2016 12:00:00 AM	\$59.70	Hourly

Material

Material					
Material Cost	Description	Material UID	Mat Unit	Units	
			Cost	Required	

Entities

Entity UID	Entity Type
13341	SANITARYSEWERCOLLECTIONSYSTEM

Custom Field Names	Custom Field Value
HOT SPOT	
BACKUP INTO PRIVATE PROPERTY	
SEWER LATERAL REPORT	
CAUSED BY ROOTS	

CAUSED BY FATS-OIL-GREASE	
CAUSED BY DEBRIS	
CAUSED BY COLLAPSE	
CAUSED BY INFILTRATION	
CAUSED BY VANDALISM	
CAUSED BY FLOW > CAPACITY	
CAUSED BY PIPE PROBLEM/FAILURE	
CAUSED BY PUMP STATION FAILURE	
CAUSED BY UNKNOWN	
CAUSED BY OTHER	
CAUSED BY OTHER - SPECIFY	
RECOMMEND CCTV	
RECOMMEND RODDING	
RECOMMEND FLUSHING	
RECOMMEND FURTHER CLEAN-UP	
RECOMMEND ADD TO PM	
RECOMMEND ADJUST PM SCHED/METH	
RECOMMEND REPAIR	
RECOMMEND REHABILITATION	
RECOMMEND REPLACE	
RECOMMEND ENFORCE FOG SOURCE	
RECOMMEND OTHER	
RECOMMEND OTHER - SPECIFY	
(LAT) CHECKED BY	
(LAT) SOURCE OF COMPLAINT	
(LAT) NATURE OF COMPLAINT	
(LAT) ACTION - DYE TEST	
(LAT) ACTION - NESTER TEST	
(LAT) ACTION - VISUAL ONLY	
(LAT) ACTION - RESULTS	
(LAT) TESTED FROM	
(LAT) LOCATED IN	
(LAT) AFFECTS PUBLIC PROPERTY	
(LAT) PUBLIC PROPERTY -SPECIFY	
(LAT) VISUAL CHECK	
(LAT) DYE SHOW MAIN IN STREET	
(LAT) DYE SHOW MAIN IN EASEMEN	
(LAT) DYE SHOW IN OTHER	
(LAT) DYE SHOW IN OTHER-SPECIF	
(LAT) ROOF DRAIN CONNECT SEWER	
(LAT) ROOF DRAIN - SPECIFY	
(LAT) CHECKED AND CLEAR	
(LAT) OWNER CONTACTED	
(LAT) OWNERS NAME	
(LAT) REMARKS	
(OFFICE) DATE FAXED	
CITY PROJECT NUMBER	
USA TICKET NUMBER	
CLEANING OBSERVATION - DEBRIS	1 Cloor
CLEANING OBSERVATION - DEBRIS  CLEANING OBSERVATION - GREASE	1 - Clear
	1 - Clear
CLEANING OBSERVATION - ROOTS	1 - Clear
CLEANING OBSERVATION - OTHER	1 - Clear
CLEANING OBSERVATION - OTHER	

Associated Service Request									
Request ID	Request Description	Request	Incident	Date & Time	Submit To	Category	Status		
-		Priority	Address	Initiated		1000 00			

First Name	Last Name	Customer Email	Cell Phone	Home Phone	Work Phone	Other Phone	Date & Time Of Call	
								_