Request # 20996 + 20997



Update Results



Address History with Comments Log

CONTACT_TYPE = Complainant, Neighbor, Tenant/Occupant, Applicant, Lienee

CONTACT_TYPE = Blank STREET NBR = 369

STREET_NAME: Begins With macarthur

STREET_TYPE : Begins With

APN = ----

DATE_OPENED >= 1/1/2011 DATE_OPENED <= 12/31/2017

RECORD_TYPE_SUBTYPE <> Soft Story Retrofit Validation

RECORD_TYPE_TYPE <>

Record ID: <u>1604420</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Putting up a barbwire on the building., Also blocking window with sign in the front of the property. Debris on the front yard.

Date Opened: 11/18/2016 Record Status: Abated

Record Status Date: 2/15/2017

Job Value: \$0.00 Requestor:

.

Business Name:

License #:

LICCHSC W.		
COMMENT DATE	COMMENTER	COMMENTS
12/19/2016	EANDERSON	Ownership verified through County Assessor, NOV mailed reg & cert with appeal form and brochures on 12/16/16.cert #70160340000000293520 Re-inspection Deadline:2/6/17
2/15/2017	CCANDELL	Date: $1/12/2017$ Site visit, photos taken. The blight issues have been resolved. The graffiti has been removed. The violation is abated. CMC X 6986
1/12/2017	CCANDELL	Date: $1/12/2017$ Site visit, photos taken. The blight issues have been resolved. The graffiti has been removed. The violation is abated. CMC X 6986
12/2/2016	CCANDELL	Site visit, photos taken. I observed the following blighted conditions: tires, a mattress, general garbage and debris, construction debris mostly located within the walls of the former garage (now roofless), also graffiti on the walls of the former garage. In addition I noted deteriorated signage made up of various materials plus barb wire on the upper story of the building. The upper floor windows where the sign is located are obstructed by the sign. The building is in a state of disrepair with many signs of rot and decay in the windows, trim, and rafter tails. The building may no longer be weather tight. The violation is confirmed. I sent a Notice of Violation to the property owner of record. CMC x 6986

Record ID: <u>1700196</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Rear unit: cracked windows, loose shower tiles/base.

Date Opened: 1/17/2017 Record Status: Closed

Record Status Date: 4/25/2017

Job Value: \$0.00 Requestor: : J.A.

Business Name:

License #:

COMMENT DATE	COMMENTER	COMMENTS
1/19/2017	WLOO	1/18/17 - inspection verified cracked window pane in bedroom & kitchen; no smoke detector in bedroom; shower stall surround deteriorated; wall surrounding furnace defective plaster; water heater no straps, missing T&P relief piping (no permit in record); building permit issued for removing this addition which is not documented by city records. wloo
2/24/2017	CCANDELL	Accidently changed status to Abated when inspection was scheduled for me (which was incorrect, I have already abated the zoning case originally assigned to me, 1604420). I have reverted the status to where it should be given the rest of the record, Violation Verified.
4/25/2017	WLOO	4/25/17 - close housing complaint due to the occupant not living in the unit, partial demolition of the unit and active building permit. whoo
3/27/2017	WLOO	3/23/17 - supervisor asked me to remove the stop work notice because the building permit was active; the property owner had email receipt of the permit extension; our office did not change the status in Accela; I went out to the property; the stop work notice has been removed; no one was at the site; took pictures. wloo
3/22/2017	WLOO .	3/22/17 - visited property to post "stop work" notice and "restricted use" (yellow tag) posting; when I got there, the rear addition framing was 95% gone; I instructed workers not to do anymore demo but can cleanup debris on the ground; the unit was not occupied; took pictures. wloo
3/22/2017	WLOO .	3/21/17 - received call from Tim Low to meet police at property; met with 2 police officers; they were concerned with the condition of the rear unit which the complainant was inside; according to the police, the owner had workers remove the siding and roof covering; most of the siding and roof covering had been removed where the living room and bathroom are; the occupant had tried to tarp the roof; went inside and noted cracks in the ceiling plaster; none had collapsed; there were wallboards removed in the bedroom and kitchen exposing the unit to other interior spaces of the building; according to the occupant, gas and water have been shut off; one of the light was on; took pictures; there was a person from channel 2 recording with a video camera the activity; I left the site to confer with Tim Low if the unit should be "tagged"; the demo permit had expired which I will post a Stop Work notice tomorrow. wloo
2/27/2017	WLOO	2/27/17 - received owner info by email from property owner, Gene Gorelik , Principal - Oakland Redevelopment Group

Record ID: <u>1701395</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Very big inflatable figure with American Flag colors and sign "#Fake News" propped on top of property along with a banner "KTVU FOX 2" place in front of property.

Date Opened: 4/3/2017

Record Status: Notice of Violation Sent Record Status Date: 4/11/2017

Job Value: \$0.00 Requestor:

Business Name:

License #:

COMMENT DATE

COMMENTER

COMMENTS

4/10/2017

ALEIGHTON

Ownership verified through County Assessor, NOV mailed reg & cert with appeal form on 4/11/17. Cert mailing #7016 0970 0000 9800 6448. Re-inspection date: 5/24/17

Record ID: 1701410

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: CONSTRUCTION WITHOUT PERMITS

Date Opened: 4/4/2017 Record Status: Non-Actionable Record Status Date: 4/10/2017

Job Value: \$0.00

Requestor:

Business Name:

License #:

COMMENT DATE

COMMENTER

COMMENTS

4/7/2017

BLAI

04-07-17 Referring to existing cases 1700196 and 1701410. Inspected property and observed partial demolition is limited to the back of property under reinstated RB1604312 but did not observe and unable to verify any work being done to the main house because majority of windows in main house have been boarded up with OSB from the inside. RE1603298 has expired and plumbing permit will be needed to complete demolition. Observed a metal storage container placed within the property on the left front side of the property where the garage would be located but is not obstructing sidewalk. There is an inflatable figure on the roof which is being inspected by zoning under case #1701395. Referring to existing cases.

Record ID: 1701676

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Excessive and annoying noise created by generator

Date Opened: 4/19/2017

Record Status:

Record Status Date: 4/19/2017

Job Value: \$0.00 Requestor:

Business Name:

License #:

COMMENT DATE COMMENTER **COMMENTS**

Record ID: *DRX161504*

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: DRX spdr to demolish rear accessory wing, built without permits, not shown on sanborn, 1 story wood, to be replaced by soil; get bp's, main house in front not changing

Date Opened: 8/29/2016 Record Status: Approved Record Status Date: 8/29/2016

Job Value: \$0.00 Requestor: : jessica sawczuk **Business Name:** License #:

COMMENT DATE COMMENTER **COMMENTS**

Record ID: <u>LM16003</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Hnit #:

Description: Heritage Property application, 369 MacArthur

Date Opened: 6/21/2016 Record Status: Filed

Record Status Date: 6/21/2016

Job Value: Requestor: : Gene Gorelik **Business Name:** License #:

COMMENT DATE

COMMENTER

COMMENTS

Record ID: *MA16003*

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Mills Act application for Lemos House, 369 MacArthur

Date Opened: 5/26/2016 Record Status: Under Review Record Status Date: 5/26/2016

Job Value: \$0.00 Requestor:

: g. gorelik, J. Sawczuk

Business Name: License #:

COMMENT DATE COMMENTER

COMMENTS

Record ID: <u>RB1604312</u> Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Remove unpermitted a story rear structure attached to 2 story SFD, remove a door and install 1 window. No work in main SFD. DRX161504

Date Opened: 9/2/2016

Record Status: Inspections - Suspended

Record Status Date: 4/10/2017

Job Value: \$5,000.00

Requestor: Jessice Sawczuk - Oakland Redevelopment Group LLC

Business Name: License #:

COMMENT DATE COMMENTER

COMMENTS

4/10/2017 DMILES Inspections suspended, debris box in public right of way , verified by Inspector Candel referred

to Public Works by B. Lai . Hold final until obstruction permit requirement is satisfied.

4/27/2017 BLAI 04-20-17 Forwarded information with photo from inspector Candell showing debris box on street.

PW informed property owner to pay for OB permit in order to remove hold on building permit. BL x6148

Record ID: *RE1603298*

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Electrical/ Remove unpermitted 1 story rear structure attached to 2 story SFD, remove a door and install 1 window. No work in main SFD. DRX161504

Date Opened: 9/2/2016
Record Status: Expired
Record Status Date: 3/1/2017

Job Value: \$0.00

Requestor: Jessice Sawczuk - Oakland Redevelopment Group LLC

Business Name: License #:

COMMENT DATE COMMENTER

COMMENTS

Record ID: ZP160089

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Pre-Application to modify an (e) sfr into a 7 unit multifamily residence, with 7 parking spaces. Property is rated Cb-2+.

Date Opened: 12/23/2016 Record Status: Under Review Record Status Date: 1/5/2017

Job Value: \$0.00 Requestor: : Gene Gorelik Business Name: License #:

COMMENT DATE COMMENTER

COMMENTS

For real-time, direct access to

information via the Internet, 24 hours a day - https://aca.accela.com/oakland

D

Update Results



Address History with Inspection Log

CONTACT_TYPE = Complainant, Neighbor, Tenant/Occupant, Applicant, Lienee

CONTACT_TYPE = Blank STREET NBR = 369

STREET NAME: Begins With macarthur

STREET_TYPE : Begins With

APN = ----

DATE_OPENED >= 1/1/2011 DATE OPENED <= 12/31/2017

RECORD_TYPE_SUBTYPE <> Soft Story Retrofit Validation RECORD_TYPE_TYPE <> Lien

Record ID: <u>1604420</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Putting up a barbwire on the building.. Also blocking window with sign in the front of the property. Debris on the front yard.

Date Opened: 11/18/2016 Record Status: Abated

Record Status Date: 2/15/2017

Job Value: \$0.00 Requestor:

Business Name:

License #:				
Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
11/22/2016	Chris Candell	1st Inspection	Violation Verified	Site visit, photos taken. I observed the following blighted conditions: tires, a mattress, general garbage and debris, construction debris mostly located within the walls of the former garage (now roofless), also graffiti on the walls of the former garage. In addition I noted deteriorated signage made up of various materials plus barb wire on the upper story of the building. The upper floor windows where the sign is located are obstructed by the sign. The building is in a state of disrepair with many signs of rot and decay in the windows, trim, and rafter tails. The building may no longer be weather tight. The violation is confirmed. I sent a Notice of Violation to the property owner of record. CMC x 6986
12/15/2016	Chris Candell	Follow-up Inspection	No Abated .	Date: 12/15/2016 Site visit, photos taken. Much of the blighted issues have been removed with the exception of the graffiti and the missing windows. I did observe a

new sign that replaced the previous dilapidated sign. This sign advertises

donations to a fund the ghost ship. The sign does not pertain to goods or services on site making this sign an Advertising under the code and not allowed. I modified the NOV to reflect the changes and sent the revised notice to the property owner of record. CMC 1/12/2017 Chris Candell Follow-up Inspection Abated Date: 1/12/2017 Site visit, photos taken. The blight issues have been resolved. The graffiti has been removed. The violation is abated. CMC X 6986

Chris Candell Follow-up Inspection Cancelled Chris Candell 1st Inspection Scheduled Chris Candell Follow-up Inspection Cancelled Chris Candell Follow-up Inspection Cancelled

Record ID: 1700196

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Rear unit: cracked windows, loose shower tiles/base.

Date Opened: 1/17/2017 Record Status: Closed

Record Status Date: 4/25/2017

Job Value: \$0.00 Requestor:

Business Name:

License #:

Inspection Date Inspector Name Inspection Type Status / Result **Result Comments** 1/18/2017 Wing Loo 1st Inspection Violation Verified

Record ID: <u>1701395</u>

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit#:

Description: Very big inflatable figure with American Flag colors and sign "#Fake News" propped on top of property along with a banner "KTVU FOX 2" place in front of property.

Date Opened: 4/3/2017

Record Status: Notice of Violation Sent Record Status Date: 4/11/2017

Job Value: \$0.00 Requestor:

Business Name: License #:

Inspection Date Inspector Name Inspection Type Status / Result **Result Comments** 4/11/2017 Chris Candell 1st Inspection Violation Verified Date: 4/7/2017 Site visit, photos taken.

> There are two signs on site. One is located high above the roofline in a tree and the other takes the form of an inflatable "eagle" mounted on top of the roof with signage attached to it and kept inflated by an electric blower. I took two noise readings from the adjacent property to the northwest. To compare the noise level of the blower to the ambient noise produced by the freeway (580), I took a second set of readings from the adjacent property on the other side of a property. The signs are considered "special

signs". The violation is confirmed as the

4/28/2017

Chris Candell

Follow-up Inspection

Abated

signage is located above the roofline see Notice of Violation for details for code sections. The noise level also appears to exceed the limits of OPC 17.120.050 Noise. I sent a Notice of Violation to the property owner of record. CMC x6986

Date: 4/28/2017 I observed that the sign in the tree and the inflated eagle/sign on the rooftop are gone. The violation is abated. CMC x6986

Chris Candell

Follow-up Inspection

Scheduled

Record ID: 1701410

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: CONSTRUCTION WITHOUT PERMITS

Date Opened: 4/4/2017

Record Status: Non-Actionable Record Status Date: 4/10/2017

Job Value: \$0.00 Requestor:

Business Name: License #:

Inspection Date

Inspector Name

Inspection Type

Status / Result

4/7/2017

Benjamin Lai

1st Inspection

Referred

Record ID: 1701676

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Excessive and annoying noise created by generator

Date Opened: 4/19/2017

Record Status:

Record Status Date: 4/19/2017

Job Value: \$0.00 Requestor:

Business Name:

License #: **Inspection Date**

Inspector Name

Inspection Type

Status / Result

Result Comments

Record ID: <u>DRX161504</u> Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: DRX spdr to demolish rear accessory wing, built without permits, not shown on sanborn, 1 story wood, to be replaced by soil; get bp's, main house in front not changing

Date Opened: 8/29/2016 Record Status: Approved Record Status Date: 8/29/2016

Job Value: \$0.00 Requestor:

Business Name:

License #: **Inspection Date**

Inspector Name

Inspection Type

Status / Result

Result Comments

Record ID: *LM16003*

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Heritage Property application, 369 MacArthur

Date Opened: 6/21/2016 Record Status: Filed

Record Status Date: 6/21/2016

Job Value: Requestor:

Business Name:

License #:

Inspection Date Inspector Name

Inspection Type

Status / Result

Result Comments

Record ID: *MA16003*

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Mills Act application for Lemos House, 369 MacArthur

Date Opened: 5/26/2016 Record Status: Under Review Record Status Date: 5/26/2016

Job Value: \$0.00 Requestor:

Business Name:

License #:

Inspector Name Inspection Type Status / Result

Result Comments

Record ID: RB1604312

Address: 369 MACARTHUR BLVD

APN: 010 078502102

Inspection Date

Unit #:

Description: Remove unpermitted a story rear structure attached to 2 story SFD, remove a door and install 1 window. No work in main SFD. DRX161504

Date Opened: 9/2/2016

Record Status: Inspections - Suspended Record Status Date: 4/10/2017

Job Value: \$5,000.00

Requestor;

Business Name:

License #:

Inspection Date

Inspector Name

Inspection Type

Status / Result

Result Comments

Record ID: RE1603298

Address: 369 MACARTHUR BLVD

APN: 010 078502102 Unit #:

Description: Electrical/ Remove unpermitted 1 story rear structure attached to 2 story SFD, remove a door and install 1 window. No work in main SFD. DRX161504

Date Opened: 9/2/2016 Record Status: Expired Record Status Date: 3/1/2017

Job Value: \$0.00 Requestory

Business Name:

License #:

Inspection Date Inspector Name **Inspection Type**

Status / Result

Result Comments

Record ID: **ZP160089** Address: 369 MACARTHUR BLVD

APN: 010 078502102

Unit #:

Description: Pre-Application to modify an (e) sfr into a 7 unit multifamily residence, with 7 parking spaces. Property is rated Cb-2+.

Date Opened: 12/23/2016 Record Status: Under Review Record Status Date: 1/5/2017

Job Value: \$0.00 Requestor:

Business Name: License #:

Inspection Date Inspector Name **Inspection Type**

Status / Result

Result Comments

For real-time, direct access to information via the Internet, 24 hours a day - https://aca.accela.com/oakland

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3
- Print your name and address on the reverse so that we can return the card to you
- Attach this card to the back of the malipiece or on the front if space permits

OAKLAND REDEVELOPMENT GROUP LLC



1701395-AL-4//1//7



Article Number (Transfer from service label)

TOLK LATO BEIN ABOUT STAB

PS Form 3811, July 2015 PSN 7530-02-000-9053

OUNDAFIE WHIS SERVION ON DESIGNERY

A COLORED B. Received by [Plinter Name]

Date of Delivery -Addressee

D. Is delivery address different from item 1? If YES, enter delivery address below:

名こでですスペ

- Service Type
- D ACIES Signature
- Adult Signature Restricted Delivery Certified Malico
- Carting Mail Restricted Delivery
- のではいると
- Collect on Delivery Restricted Delivery
- HI Restricted Delivery

- I Profy Mail Typresse
- I Registered Mail The
- ☐ Registered Mail Restricter
- II Noum Receipt for Merchandise
- ☐ Signature Confirmation™
 ☐ Signature Confirmation
- Restricted Delivery

Compalio Ratum Receipt



250 FRANK H. OGAWA PLAZA - SUITE 2340 - OAKLAND, CALIFORNIA 94612-2031

Planning and Building Department Building Permits, Inspections and Code Enforcement Services www.oaklandnet.com (510) 238-6402 FAX:(510) 238-2959 TDD:(510) 238-3254

NOTICE OF VIOLATION

Date: 4/7/17

Certified and Regular mail

To: Oakland Redevelopment Group LLC

Code Enforcement Case No.: 1701395
Property: 369 Macarthur Blvd.
Parcel Number: 010-0785-021-02
Correction Due Date:5/24/17

Code Enforcement Services inspected your property on 4/4/17 and confirmed that the violations of the Oakland Municipal Code (OMC) identified below are present and need to be addressed as specified under 'Required Actions'. Photographs of the violations are enclosed where applicable.

Description of the following property of the p	UNIC Section	Kequirea Action
Property		
The state of the s	<u> </u>	
	# 5	
D.: 1131	I THE THE PROPERTY OF THE PROP	Consider annualisation are commissioners or distinct to constitution and annual residence of the constitution of the constitut
Building		
		•
	·	
Zoning	- Print File Freeholder (More till Freeholder) selections (More selections) (More selections)	
This property is located in the RU-2/S-12 zone. The	17.19.020 Required	Remove the signage &
signage on the roof and the signage on the tree are subject	Design Review Process,	blower, or
to Design Review approval. There is no Design Review	17.108.030 (k) Allowed	Obtain Planning approval for
approval for this signage on file. Signage is subject to but	projections above height	the signage, and
not limited to the following cited codes.	limits,	Reduce the noise level of the
	17.104.010 A. B. C. D.	blower to meet the cited
In addition, the blower used to keep the sign inflated is	E. F. G. 1, 2, 3, General	section.
		Scotton.
producing noise in excess of that allowed in the	limitations on Signs in	
Performance Standards.	Residential zones, except	,
	RU-4 & RU-5 Zones &	
	in Open Space (OS)	
	Zones,	
	17.120.050 Noise	

July, 2015 Scan to: Code Enforcement-Chronology-Abatement Activities

Notice of Violation Page 2of 2

At this point no fees or other charges have been assessed for these violations. To stop further code enforcement action, you are advised to correct the above violations <u>before the first re-inspection date shown below</u>. Your inspector is available by phone at 510-238-6986 and by email at ceandel@oaklandnet.com.

Note: If a complaint is filed regarding the same or similar violation(s) and it is confirmed within 24 months from the date of this notice an immediate assessment of \$1,176.00 will be charged as a Repeat Violation. In addition, if violation(s) remain uncorrected after receiving a 30 day Notice of Violation further enforcement action(s) will include additional fees.

If the re-inspection verifies that all violations have not been corrected, you may be charged for inspection and administrative costs, which can total \$2,665.00. In addition, Priority Lien fees in the amount of \$1,926.00 may be assessed if fees are not paid within 30 days from the date of the invoice. Charges may be collected by recording liens on your property and adding the charges to your property taxes or by filing in Small Claims or Superior Court. Furthermore, this Notice of Violation may be recorded on your property.

You have a right to appeal this Notice of Violation. To file an appeal, you must complete the enclosed Appeal form and pay the filing in the amount of \$110.00 and return it with supporting documentation in the enclosed envelope. If the Code Enforcement Division does not receive your written Appeal within 30 days of the date of this notice, you will waive your right for administrative review.

Sincerely,
(Lews Cambell

Chris Candell Planner III

Planning and Building Department

First Fee Charged Re-inspection Date: 5/24/17

Second Fee Charged Re-inspection Date: 6/7/17

Administrative Hearing Fees

Filing Fee \$ 110.00

Conduct Appeals Hearing Actual Cost Appeal (Fee charged only if Appellant loses appeal)

Processing Fee \$ 931,00 Reschedule Hearing \$ 329.00

Fee Includes 9.5% Records Management Fee and 5.25% Technology Enhancement Fee

cc:

County Assessor Display

Assessor Parcel Record for APN 010--0785-021-02

Parcel Number:	10-785-21-2
Property Address:	369 MACARTHUR BLVD, OAKLAND 94610
Owner Name:	OAKLAND REDEVELOPMENT GROUP LLC
Care of:	
Attention:	
Mailing Address:	
Use Code:	SINGLE FAMILY RESIDENTIAL HOMES USED AS SUCH
Recorder Number:	2016-125465
Recorder Date:	5/18/2016
Mailing Address Effective Date:	5/18/2016
Last Document Input Date:	8/19/2016
Deactivation Date:	
Exemption Code:	

Home

Enter Assessor Parcel Number

Assessments

Property Details GIS Parcel Map Alameda County Web Site

Use Codes



SENDER: COMPLETE THIS SECTION COMPLETE THIS SECTION ON DELIVERY ■ Complete items 1, 2, and 3. ☐ Agent Print your name and address on the reverse Addressee so that we can return the card to you. C. Date of Delivery even by (Printed Name) Attach this card to the back of the mailpiece, or on the front if space permits. 5.99 1. Article Addressed to: D. Is delivery address different from item 1? ☐ Yes DAKLAND REDEVELOPMENT GROUP LLC MACARTHUR BLVD/1604420/CC/EA/12/16/16 3. Service Type Adult Signature Adult Signature Restricted Delivery Certified Mail® Certified Mail Restricted Delivery ☐ Priority Mail Express® □ Priority Mall Express® ☐ Registered Mall™ ☐ Registered Mall™ ☐ Return Receipt for Merchandise ☐ Signature Confirmation™ ☐ Signature Confirmation Restricted Delivery ☐ Collect on Delivery ☐ Collect on Delivery Restricted Delivery 2 Article Number (Transfer from service label) 7016 0340 0000 0029 3520 lail Restricted Delivery

PS Form 3811, July 2015 PSN 7530-02-000-9053

Domestic Return Receipt



250 FRANK H. OGAWA PLAZA • SUITE 2340 • OAKLAND, CALIFORNIA 94612-2031


Planning and Building Department
Building Permits, Inspections and Code Enforcement Services
www.oaklandnet.com

(510) 238-6402 FAX:(510) 238-2959 TDD:(510) 238-3254

NOTICE OF VIOLATION

Date: 12/16/16

Certified and Regular mail



Code Enforcement Case No.: 1604420 Property: 369 Macarthur Blvd. Parcel Number: 010-0785-021-02 Correction Due Date; 2/6/17

Code Enforcement Services inspected your property on 11/22/16 & 12/14/16 and confirmed that the violations of the Oakland Municipal Code (OMC) identified below are present and need to be addressed as specified under 'Required Actions'. Photographs of the violations are enclosed where applicable.

Description of Violation	OMC Seation	
Property	And the second s	
Building		
The following constitute blight: grafitti on former garage walls, barb wire attached to the front elevation, broken or missing windows, plywood covering the front windows.	8.24.020 Blighted Property Defined C. 2,3,4 D. 1, 7.	Remove 6grafitti, remove barb wire, repair broken windows, and remove plywood covering front windows/facade.
Zoning		
The signage attached to the front elevation does not advertise for a product or service offered on site. This makes the sign an "Advertising Sign". Such signage is not permitted or conditionally permitted in the RU-2/S-12 residential zone where your property is located. In addition, any signage requires Design Review Approval; there is no Design Review approval on file.	17.19. 040 and table 17.19.02 Permitted and Conditionally Permitted Facilities, 17.19.020 Design Review Process.	Remove the signage, or Obtain Planning approval for the sign.
]	1 .

Notice of Violation Page 1 of 2 Notice of Violation Page 2of 2

At this point no fees or other charges have been assessed for these violations. To stop further code enforcement action, you are advised to correct the above violations before the first re-inspection date shown below. Your inspector is available by phone at 510-238-6986 and by email at ccandell@oaklandnet.com.

Note: If a complaint is filed regarding the same or similar violation(s) and it is confirmed within 24 months from the date of this notice an immediate assessment of \$1,176.00 will be charged as a Repeat Violation. In addition, if violation(s) remain uncorrected after receiving a 30 day Notice of Violation further enforcement action(s) will include additional fees.

If the re-inspection verifies that all violations have not been corrected, you may be charged for inspection and administrative costs, which can total \$2,665.00. In addition, Priority Lien fees in the amount of \$1,926.00 may be assessed if fees are not paid within 30 days from the date of the invoice. Charges may be collected by recording liens on your property and adding the charges to your property taxes or by filing in Small Claims or Superior Court. Furthermore, this Notice of Violation may be recorded on your property.

You have a right to appeal this Notice of Violation. To file an appeal, you must complete the enclosed Appeal form and pay the filing in the amount of \$110.00 and return it with supporting documentation in the enclosed envelope. If the Code Enforcement Division does not receive your written Appeal within 30 days of the date of this notice, you will waive your right for administrative review.

Sincerely,

Chris Candell Planner III

Planning and Building Department

Candle

First Fee Charged Re-inspection Date: 2/6/17

Second Fee Charged Re-inspection Date: 2/21/17

Administrative Hearing Fees

Conduct Appeals Hearing

Processing Fee Reschedule Hearing

Actual Coat Appeal (Fee charged only, if Appellant loses appeal)
5.931:00

\$ 329.00

CC:

Encl: Violation Appeal Form



County Assessor Display


Assessor Parcel Record for APN 010--0785-021-02

Parcel Number:	10-785-21-2
Property Address:	369 MACARTHUR BLVD, OAKLAND 94610
Owner Name:	OAKLAND REDEVELOPMENT GROUP LLC
Care of:	
Attention:	
Mailing Address:	
Use Code:	SINGLE FAMILY RESIDENTIAL HOMES USED AS SUCH
Recorder Number:	2016-125465
Recorder Date:	5/18/2016
Mailing Address Effective Date:	5/18/2016
Last Document Input Date:	8/19/2016
Deactivation Date:	
Exemption Code:	

Home Assessor
Parcel
Number

Assessments Property GIS Parcel
Details Map
Web Site

U.S. Postal Service CERTIFIED MAIL® RECEIPT



Use Codes



250 FRANK H. OGAWA PLAZA • SUITE 2340 • OAKLAND, CALIFORNIA 94612-2031


Planning and Building Department
Building Permits, Inspections and Code Enforcement Services
www.oaklandnet.com

(510) 238-6402 FAX:(510) 238-2959 TDD:(510) 238-3254

NOTICE OF VIOLATION

Date: 12/16/16

Certified and Regular mail



Code Enforcement Case No.: 1604420 Property: 369 Macarthur Blvd. Parcel Number: 010-0785-021-02 Correction Due Date:2/6/17

Code Enforcement Services inspected your property on 11/22/16 & 12/14/16 and confirmed that the violations of the Oakland Municipal Code (OMC) identified below are present and need to be addressed as specified under 'Required Actions'. Photographs of the violations are enclosed where applicable.

Description of Violation	OMC Sention	Riconfred Adilbit
Property		
	*	
Building		
The following constitute blight: grafitti on former garage walls, barb wire attached to the front elevation, broken or missing windows, plywood covering the front windows.	8.24.020 Blighted Property Defined C. 2,3,4 D. 1, 7.	Remove 6grafitti, remove barb wire, repair broken windows, and remove plywood covering front windows/facade.
7		
Zoning The signage attached to the front elevation does not	17.19, 040 and table	Demous the signess or
advertise for a product or service offered on site. This	17.19.040 and table	Remove the signage, or Obtain Planning approval for
makes the sign an "Advertising Sign". Such signage is not	Conditionally Permitted	the sign.
permitted or conditionally permitted in the RU-2/S-12	Facilities, 17.19.020	
residential zone where your property is located. In	Design Review Process.	
addition, any signage requires Design Review Approval;		
there is no Design Review approval on file.		

Notice of Violation Page 1 of 2 Notice of Violation Page 2of 2

At this point no fees or other charges have been assessed for these violations. To stop further code enforcement action, you are advised to correct the above violations before the first re-inspection date shown below. Your inspector is available by phone at 510-238-6986 and by email at ccandell@oaklandnet.com.

Note: If a complaint is filed regarding the same or similar violation(s) and it is confirmed within 24 months from the date of this notice an immediate assessment of \$1,176.00 will be charged as a Repeat Violation. In addition, if violation(s) remain uncorrected after receiving a 30 day Notice of Violation further enforcement action(s) will include additional fees.

If the re-inspection verifies that all violations have not been corrected, you may be charged for inspection and administrative costs, which can total \$2,665.00. In addition, Priority Lien fees in the amount of \$1,926.00 may be assessed if fees are not paid within 30 days from the date of the invoice. Charges may be collected by recording liens on your property and adding the charges to your property taxes or by filing in Small Claims or Superior Court. Furthermore, this Notice of Violation may be recorded on your property.

You have a right to appeal this Notice of Violation. To file an appeal, you must complete the enclosed Appeal form and pay the filing in the amount of \$110.00 and return it with supporting documentation in the enclosed envelope. If the Code Enforcement Division does not receive your written Appeal within 30 days of the date of this notice, you will waive your right for administrative review.

Sincerely.

Chris Candell Planner III

Planning and Building Department

Carello D

First Fee Charged Re-inspection Date: 2/6/17

Second Fee Charged Re-inspection Date: 2/21/17

Administrative Hearing Fees

Conduct Appeals Hearing

Processing Fee

Reschedule Hearing

Actual Cost Appeal (Fee charged only if Appellant loses appeal)

\$ 329.00

Fee Includes 9.5% Records Management Fee and 5.2.

cc:

Encl: Violation Appeal Form



County Assessor Display

Assessor Parcel Record for APN 010--0785-021-02

Parcel Number:	10-785-21-2
Property Address:	369 MACARTHUR BLVD, OAKLAND 94610
Owner Name:	OAKLAND REDEVELOPMENT GROUP LLC
Care of:	
Attention:	
Mailing Address:	
Use Code:	SINGLE FAMILY RESIDENTIAL HOMES USED AS SUCH
Recorder Number:	2016-125465
Recorder Date:	5/18/2016
Mailing Address Effective Date:	5/18/2016
Last Document Input Date:	8/19/2016
Deactivation Date:	
Exemption Code:	

 $\frac{\text{Home}}{\text{Home}} = \frac{\frac{\text{Enter}}{\text{Assessor}}}{\frac{\text{Parcel}}{\text{Number}}}$

Assessments Property OIS Parcel County Use Codes

Map Web Site



COMPLETE THIS SECTION ON DELIVERY SENDER: COMPLETE THIS SECTION A. Sigga ■ Complete items 1, 2, and 3. □ Agent Print your name and address on the reverse so that we can return the card to you. ☐ Addressee 2 · 33 · 1 Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: D. . ☐ Yes If YES, enter delivery address below: □ No OAKLAND REDEVELOPMENT GROUP LLC 369 MACARTHUR BLVD/1604420/CC/EA/12/16/16 □ Priority Mail Express® □ Registered Mail™ □ Registered Mail Restricted Delivery □ Return Receipt for Merchandise □ Signature Confirmation™ □ Signature Confirmation Restricted Delivery Service Type D Adult Signature ☐ Adult Signature Restricted Delivery ☐ Certified Mail® ☐ Certified Mail® Collect on Delivery Collect on Delivery Collect on Delivery Restricted Delivery 2 Article Number (Transfer from service label) 7016 0340 0000 0029 3520 lail Restricted Delivery

PS Form 3811, July 2015 PSN 7530-02-000-9053

Domestic Return ricceipt