## Work Order 556821

Work Order ID #	556821
Work Order Category	Sewers
Work Order Description	Sewers - Clean - Flush
Work Order Address	3310 COURTLAND AV
Submit To	LEACH, THOMAS B

From Request 485130: Code: SE\_BLOCKAGE

Description: Sewers - Blockage

Details:

Comments: By CAI, ZHEN: 10/9/2013 4:14:03 PM

CITIZEN IS REPORTING SEWER LEAK FROM HER NEIGHBOR'S HOUSE, ALL THE WAY DOWN TO THE CITIZEN'S BACK WALKWAY, GARAGE, ETC. AT 3310 COURTLAND

AVENUE. SEWER IS COMING FROM 4410 CAMDEN STREET.

Caller: TOUSSAINT, PATRICIA:

Q: Is the sewage outside or inside the house?

A: Outside

Q: Where is it coming from?

A: Other

Q: Is the flow steady or intermittent?

A: Steady

By CAI, ZHEN: 10/9/2013 4:15:29 PM

PLEASE CONTACT CITIZEN WHEN CREW IS IN THE FIELD.

By CAI, ZHEN: 10/9/2013 4:18:42 PM REPORTED TO T. JONES.

By LEACH, THOMAS B: 10/11/2013 3:35:34 PM

FOUND THAT BASEMENT AT 4410 CAMDEN AV WAS FLOODED AND FULL OF SEWAGE THAT IS SEEPING ALL UNDER NEIGHBORS HOME AT 3310 COURTLAND AVE. TOOK PICTURES AND FILLED A SIDE SEWER INVESTIGATION REPORT, FLUSHED ALL SEWER MAINS IN AREA, THEY ARE CLEAR AND FLOWING. THIS IS NOT A SEWER ISSUE.

Priority	Medium
Supervisor	NICKS, JOHNNY R
Cityworks Project Name	
Initiated By	LEACH, THOMAS B
Initiated Date	10/9/2013 7:09:32 PM
Actual Start Date	10/9/2013 4:30:36 PM
Actual Finish Date	10/9/2013 8:00:00 PM
Police Beat	28X
Service Delivery District	5
City Council District	CCD4
Total Entities (GIS Assets) on Work Order	6
Units Accomplished	600
Units Accomplished Description	Linear Feet
Total Work Order Cost	\$607.53
Total Of Work Order Labor Costs	\$472.08
Total Of Work Order Material Costs	\$0.00
Total Of Work Order Equipment Costs	\$135.45

## Labor

Labor Cost	Labor Name	Hours	Start Date	Finish Date
\$206.78	HIGHTOWER, JR., ALBERT G	3.50	10/9/2013 4:30:53 PM	10/9/2013 8:00:04 PM
\$265.30	LEACH, THOMAS B	3.50	10/9/2013 4:30:53 PM	10/9/2013 8:00:04 PM

Equipment
-----------

- 4 - 1 - 1 - 1 - 1 - 1							
Equipment	Description	Equip ID	Hours	Start Date	Finish Date	Equip Unit	Equipment
Cost	•					Cost	Rate Type



Wot 556881

Fax to: Sewer & Utility Inspection Section (Phone No. 238-2235)  Pax from: Sewer Maintenance Division  Date Faxed: 10-10-11
Address: 4410 Camden SP, Date: 10/9/13
Checked by: T. Lench Source of complaint:
Nature of complaint: Sternest From Home soturations neighbor yard
Action taken: Dye Test Nestler Test Visual Only Results were: Positive Negative
Tested From: Cave Depression Sink Toilet Wash Trays Bathtub
☐ Rat hole ☐ Other
Located in: Street Gutter Public Sidewalk Yard (front - rear - side) kitchen
☐ Bathroom ☐ Basement ☐ Out- building
Does the condition of sewer affect other properties of the public?  Yes No If yes, explain under "remarks"
Was a Visual check during sewer main repair or reconstruction?
The dye [ (did) [ (did not) show in the main in the [ Street [ Easement [ Yard (front - rear - side)
Are roof drains connected to the building sewer? Yes You If yes, explain under "remarks".
Was the sewer main checked at this time and determined to be clear?
Was the owner of this property contacted at the time of testing and shown the above marked condition? Yes 4No Owner's name:
Remarks: Veighbor At 3310 Courtland Av. has stavege Flowing from This homes basement All under their home and into their
90005E, Their yard is saturated with the water from
Signature or Supervisor: Muguel August