



## Update Results



## Address History with Inspection Log

CONTACT\_TYPE = Applicant, Complainant, Neighbor, Occupant/Tenant, Tenant/Occupant, Vendor  
 CONTACT\_TYPE Blank  
 ADDR\_PARTIAL Begins With 1829 MYRTLE  
 APN = (blank)  
 DATE\_OPENED >= 1/1/1980  
 DATE\_OPENED <= 12/31/2020

Record ID: [SSRV151766](#)

Address: 1829 MYRTLE ST

APN: 005 040902000

Unit #:

Description: Soft Story Retrofit Validation

Date Opened: 8/10/2015

Record Status: Open Retrofit Required

Record Status Date: 8/10/2015

Job Value:

Requestor: SPJC LLC

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
-----------------	----------------	-----------------	-----------------	-----------------

Record ID: [B1401472](#)

Address: 1829 MYRTLE ST, ##3 & #4

APN: 005 040902000

Unit #: #3 & #4

Description: Non-structural kitchen remodel for Unit #3 & bath for unit #4

Date Opened: 12/29/2014

Record Status: Final

Record Status Date: 4/26/2015

Job Value: \$12,500.00

Requestor: SPJC LLC -Carlos Padilla

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
1/16/2015	Steve Brandeberry	Frame	Partial	Date: 1/16/2015 Framing, insulation and tile backer for number four bath okay. sheet rock inspection not required
4/26/2015	Bill Bergstrom	Final Building	Pass	Date: 4/26/2015 Final inspection okay

Record ID: [E1401109](#)

Address: 1829 MYRTLE ST, ##3, #4

APN: 005 040902000

Unit #: #3, #4

Description: Electrical for non-structural kitchen remodel for Unit #3 & bath for unit #4. Add two circuits for kitchen receptacles in unit #5. No change to light fixtures in any unit.

Date Opened: 12/29/2014

Record Status: Final

Record Status Date: 4/26/2015

Job Value: \$0.00

Requestor: SPJC LLC -Carlos Padilla

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
1/16/2015	Steve Brandeberry	Frame	Partial	

1/21/2015	Joel Garcia	Frame	Partial	Wire, light & fan at unit #4 bath OK. Will need to turn sub panel face around from closet to hallway.
4/26/2015	Bill Bergstrom	Final Electrical	Pass	Rough OK unit # 3
				Date: 4/26/2015 Final okay

**Record ID:** [P1400822](#)**Address:** 1829 MYRTLE ST, ##3 & #4**APN:** 005 040902000**Unit #:** #3 & #4**Description:** Plumbing for non-structural kitchen remodel for Unit #3 & bath for unit #4**Date Opened:** 12/29/2014**Record Status:** Final**Record Status Date:** 4/27/2015**Job Value:** \$0.00**Requestor:** SPJC LLC -Carlos Padilla

:

**Business Name:****License #:**

<b>Inspection Date</b>	<b>Inspector Name</b>	<b>Inspection Type</b>	<b>Status / Result</b>	<b>Result Comments</b>
1/16/2015	Steve Brandeberry	Frame	Partial	shower valve and tub test for unit #4 bath OK. EAD (E).
4/27/2015	William Moriarty	Final Plumbing	Pass	Date: 4/24/2015 On site at 11 o'clock contractor not on site. Contractor will not be on site for 20 to 30 minutes will have to reschedule. Final inspection completed by WMB.

**Record ID:** [SS111405](#)**Address:** 1829 MYRTLE ST**APN:** 005 040902000**Unit #:****Description:** EXEMPTED - NO COMMERCIAL OR PARKING SPACE ON GROUND LEVEL**Date Opened:** 12/19/2011**Record Status:** Expired**Record Status Date:** 9/18/2012**Job Value:** \$0.00**Requestor:** SPJC LLC

:

**Business Name:****License #:**

<b>Inspection Date</b>	<b>Inspector Name</b>	<b>Inspection Type</b>	<b>Status / Result</b>	<b>Result Comments</b>
------------------------	-----------------------	------------------------	------------------------	------------------------

**Record ID:** [B0805033](#)**Address:** 1829 MYRTLE ST, ##7**APN:** 005 040902000**Unit #:** #7**Description:** Bathroom remodel of tub/shower enclosure and vanity for unit # 7 of existing 7 unit apartment building (per sanborn)**Date Opened:** 11/25/2008**Record Status:** Final**Record Status Date:** 12/11/2008**Job Value:** \$2,000.00**Requestor:** SPJC LLC

:

**Business Name:****License #:**

<b>Inspection Date</b>	<b>Inspector Name</b>	<b>Inspection Type</b>	<b>Status / Result</b>	<b>Result Comments</b>
12/1/2008	WILLIAM M BERGSTROM	TUB/SHOWER WALL 03N	CORRECTION NOTICE	R/ CARLOS 750-3328
12/3/2008	JANICE J KATO	TUB/SHOWER WALL 03N	INSP NOT PERFORMED	TYVEK NOT A VAPOR BARRIER
12/4/2008	JANICE J KATO	TUB/SHOWER WALL 03N	APPROVED	CEMENTBOARD AT T/S WALL
12/11/2008	WILLIAM M BERGSTROM	FINAL BUILDING 04P	APPROVED	

**Record ID:** [P0802942](#)**Address:** 1829 MYRTLE ST, ##7**APN:** 005 040902000**Unit #:** #7**Description:** Plumbing permit for Bathroom remodel of tub/shower enclosure and vanity for unit # 7 of existing 7 unit apartment building (per sanborn)**Date Opened:** 11/25/2008**Record Status:** Expired**Record Status Date:** 12/8/2009**Job Value:** \$0.00**Requestor:** SPJC LLC

:

**Business Name:****License #:**

<b>Inspection Date</b>	<b>Inspector Name</b>	<b>Inspection Type</b>	<b>Status / Result</b>	<b>Result Comments</b>
------------------------	-----------------------	------------------------	------------------------	------------------------

12/1/2008 DAVID C CARRILLO ROUGH 03P PARTIAL APPROVAL H2O MIXER D.W.V. EXISTING TUB T/C  
 12/11/2008 REYNOLDO T JIMENEZ ROUGH 03P APPROVED FINAL 86 98 1050 1100

**Record ID:** [0808054](#)

**Address:** 1829 MYRTLE ST

**APN:** 005 040902000

**Unit #:**

**Description:** BATHROOM REMODEL W/O PERMIT, NEW TUB AND ENCLOSURE, STOP WORK ISSUEDON 11/24/08

**Date Opened:** 11/24/2008

**Record Status:** Open

**Record Status Date:**

**Job Value:** \$0.00

**Requestor:**

:

**Business Name:**

**License #:**

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
11/24/2008	EUGENE MARTINELLI	1st Inspection	Violation Verified	STOP WORK ORDER ISSUED
11/25/2008	EUGENE MARTINELLI	1st Inspection	No Entry	SCHEDULED IN ERROR
11/26/2008	EUGENE MARTINELLI	1st Inspection	Violation Verified	STOP WORK ORDER ISSUED
1/8/2009	EUGENE MARTINELLI	OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1	Complaint ABated	ABATED
1/8/2009	EUGENE MARTINELLI	OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1	Complaint ABated	ABATED

**Record ID:** [08040521](#)

**Address:** 1829 MYRTLE ST

**APN:** 005 040902000

**Unit #:**

**Description:** reserve for move

**Date Opened:** 8/24/2004

**Record Status:** Application Approved

**Record Status Date:**

**Job Value:** \$0.00

**Requestor:** JUAN PEREZ

:

**Business Name:**

**License #:**

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
-----------------	----------------	-----------------	-----------------	-----------------

**Record ID:** [0103383](#)

**Address:** 1829 MYRTLE ST, #1

**APN:** 005 040902000

**Unit #:** 1

**Description:** PLUMBING IS DEFECTIVE TOILET PLUGGED - KITCHEN FAUCET LEAKFRONT YARD IS OVERGROWN AND HAS TRASH AN DEBRIS

**Date Opened:** 4/30/2001

**Record Status:** Abated

**Record Status Date:** 8/23/2002

**Job Value:** \$0.00

**Requestor:** T/SHAMEL COBURN

:

**Business Name:**

**License #:**

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
5/1/2001		1st Inspection	No Entry	Scheduled inspection voided by result code 98 on 08/23/02
6/4/2001		1st Inspection	No Violations	
6/8/2001		OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1	Substantial compliance/no fees	
6/12/2001		1st Inspection	No Entry	RESCHEDULED FOR 6/13/01
6/13/2001		1st Inspection	No Entry	RESCHEDULED FOR 6/19/01
6/13/2001		1st Inspection	No Entry	RESCHEDULED FOR 6/19/01
6/19/2001		1st Inspection	No Entry	RESCHEDULED FOR 6/22/01
6/19/2001		1st Inspection	No Entry	RESCHEDULED FOR 6/22/01
6/22/2001		1st Inspection	No Entry	RESCHEDULED FOR 7/09/01
6/22/2001		1st Inspection	No Entry	RESCHEDULED FOR 7/09/01
7/9/2001		1st Inspection	No Entry	Scheduled inspection voided by result code 98 on 08/23/02
8/15/2002		1st Inspection	No Entry	NO COMMENT
8/15/2002		OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1	Inspection re-scheduled	NO COMMENT
8/23/2002		1st Inspection	Violation Verified	Reinsp generated from insp result 82 on 08/15/02

**Record ID:** [9705420](#)

**Address:** 1829 MYRTLE ST

**APN:** 005 040902000

Unit #:

Description: BEAT HEALTH: 07-24-97; 11:30AM: THURSDAY

Date Opened: 7/22/1997

Record Status: Closed

Record Status Date: 7/24/1997

Job Value: \$0.00

Requestor: BEAT HEALTH

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
-----------------	----------------	-----------------	-----------------	-----------------

For real-time, direct access to information via the Internet, 24 hours a day - <https://aca.accela.com/oakland>