



Update Results



Address History with Inspection Log

CONTACT_TYPE = Applicant, Complainant, Neighbor, Occupant/Tenant, Tenant/Occupant, Vendor
 CONTACT_TYPE Blank
 ADDR_PARTIAL Begins With 4163 RIFLE
 APN = (blank)
 DATE_OPENED >= 1/1/2016
 DATE_OPENED <= 12/31/2020
 RECORD_TYPE_SUBTYPE <> Soft Story Retrofit Validation

Record ID: [RB1600583](#)

Address: 4163 RIFLE LN

APN: 040A384502500

Unit #:

Description: Legalize unapproved addition at back of house

Date Opened: 2/9/2016

Record Status: Issued

Record Status Date: 2/9/2016

Job Value: \$10,000.00

Requestor: GARAY MELINDA & LUCERO ESTHER

: BILL(L.O.A.) CHAPMAN

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
	Anthony Harbaugh	Frame	Scheduled	

Record ID: [RE1600407](#)

Address: 4163 RIFLE LN

APN: 040A384502500

Unit #:

Description: Electrical to remodel existing bathroom.

Date Opened: 2/9/2016

Record Status: Permit Issued

Record Status Date: 2/9/2016

Job Value: \$0.00

Requestor: GARAY MELINDA & LUCERO ESTHER

: BILL(L.O.A.) CHAPMAN

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
	Anthony Harbaugh	Frame	Scheduled	

Record ID: [RP1600322](#)

Address: 4163 RIFLE LN

APN: 040A384502500

Unit #:

Description: Plumbing to remodel existing bathroom.

Date Opened: 2/9/2016

Record Status: Permit Issued

Record Status Date: 2/9/2016

Job Value: \$0.00

Requestor: GARAY MELINDA & LUCERO ESTHER

: BILL(L.O.A.) CHAPMAN

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
	Anthony Harbaugh	Frame	Scheduled	

For real-time, direct access to information via the Internet, 24 hours a day - <https://aca.accela.com/oakland>
