IF SUPPLIER IS SUBJECT	Ō	Fiscal Year		City of Oakland		BATCH NUMBER		
PROMPT PAYMENT put an X in the box		2014-15	ENCUM	ENCUMBRANCE LIQUIDATION		BATCH DATE		
IF INVOICE IS DISPUTED	7 2005 2005 2005				<u> </u>	INPUT/AUDITED BY		
put an X in the box	2 2 2 1 2 2 2 1 3 1 2 2 1 3 1 2 2 2 1 3 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	SUPPLIER NUMBER	105778					
DISTRIBUTION (Check Box):		SUPPLIER NAME	VIEVU		ar and first resident		-	
HOLD FOR PICK-UP	×	ADDRESS	105 W. JOHN ST.	N ST.		TOTAL INVOICE AMOUNT	\$1,151.75	.75
ATTACHIMENT		CITY, STATE, ZIP	SEATTLE, \	TLE, WA 98119	2013 A		San E	
MAL	2 - 200 - 15 - 15 - 15 - 15 - 15 - 15 - 15 -				and the second		g sina	
I HEREBY CERTIFY THE ARTI- HAVE BEEN DELIVERED OR F	LES OR SERVICE ERFORMED AND	S DESCRIBED BY THE II THAT NO PRIOR CLAIM I	NVOICE(S) ATTACH HAS BEEN PRESEN	I HEREBY CERTIFY THE ARTICLES OR SERVICES DESCRIBED BY THE INVOICE(S) ATTACHED AND LISTED BELOW WERE NECESSARY FOR USE BY THIS AGENCY / DEPARTMENT AND HAVE BEEN DELIVERED OR PERFORMED AND THAT NO PRIOR CLAIM HAS BEEN PRESENTED FOR SAID ARTICLES OR SERVICES:	FOR USE BY THIS AGE	INCY / DEPARTIN	IENT AND	
OPD - FISCAL SERVICES	09/16/14	KAREN LU			1 Mondona.	i NIII	p -10	111111
AGENCYDEPARTMENT	DATE	PAYMENT REQUEST PREPARED BY	ARED BY		AUTHORIZATION SIGNATURE AND DATE	JRE AND DATE REQU	nikeo) (	
		510-238-7447	i		DONNESHIA TAYLOR	JR SPETATION SIGNAT	39	
	Military Service of Maria and Pro-	PHONE NUMBER (REQUIRED)	_ ľ.		PRINTED NAME OF AUT	JORIZA LION SIGNA I	UKE	STATE OF STATES
# Date Invoice   Received   Invoice Number   I   MM/DD/YY	Invoice Date	Invoice Amount	Customer or Account Number	Description (45 Characters Maximum)	PO#	Release Line	Amount	CA BOE Sales Tax
1 08/27/14 9839	07/31/14	1,151.75		BODY WORN CAMERA REPAIR	2014014210		1,128.75	
	- - 	·		SHIPPING		7	23.00	
. •								
. <b>4</b>	<u>.</u>							
್ಷ								
<b>.</b>							·	
<u>,</u>					-			
	Invoice Total	1,151.75				Total	1,151.75	ı
DETAILED DESCRIPTION	1.1010.1064	1.1010.106410.54611.0.PS01						

**Invoice** 

Page 1 of 2

Date Invoice # PO #


7/31/2014 9839 RMA104665

Bill To

Oakland Police Department Information and Technology Unit Project Resource Management 455 7th St., 9th Floor Room #900 Oakland CA 94607

## Ship To

Oakland Police Department Information and Technology Unit Project Resource Management 455 7th St., 9th Floor Room #900 Oakland CA 94607





105 W John St Seattle WA 98119 USA 888-285-4548 Fax 206.299.3380

Balance Due 1,151.75 Terms Net 30

Due Date 8/30/2014
Sales Rep
Partner
Shipping Method UPS Ground
Ship Date 7/31/2014

Tracking # 1Z6459Y80395317979

Shipping Code (2)

2014614210

1	LE2-018878	LE2 Body Worn Video Camera	0.00	Yes	0.00
1	1 .	· ·	1		
1		No errors were found during inspection or the product was repaired.		Yes	0.0
1		Returning product to customer. LE2-006043			
1	LE2-018822	LE2 Body Worn Video Camera	0.00	Yes	. 0.0
1	LE2-018876	LE2 Body Worn Video Camera	0.00	Yes	0.0
1	LE2-018884	LE2 Body Worn Video Camera	0.00	Yes	0.0
1	LE2-018824	LE2 Body Worn Video Camera	0.00	Yes	0.0
1	LE2-018823			Vac	0.0
	LLE 010020				
6		Hepair of camera.	175.00	Yes	1,050.0
5		Video files removed from camera and placed on disc	0.00		0.0
1					
				:	
		ന്തുന്നുടുത്തി		-	
		AUC O 7 Proper			
		THE WAR S / WEND /			
		X1			
		1/0			
		Λ. \			
:					
		0 /9			
					•
		1 11 11 11 11 11 11 11 11			
	11				
	.:				
10		Salal of Deni	ļ		
	1 1 5 5	1 LE2-018884  1 LE2-018824  1 LE2-018823  6 5	1 LE2-018884 LE2 Body Worn Video Camera  1 LE2-018884 LE2 Body Worn Video Camera  1 LE2-018824 LE2 Body Worn Video Camera  1 LE2-018823 LE2 Body Worn Video Camera  6 Repair of camera.	1 LE2-018894 LE2 Body Worn Video Camera 0.00 1 LE2-018824 LE2 Body Worn Video Camera 0.00 1 LE2-018823 LE2 Body Worn Video Camera 0.00 1 LE2-018823 LE2 Body Worn Video Camera 0.00 1 Repair of camera 0.00 1 Video files removed from camera and placed on disc 0.00  DECETIVE  AUG 2 7 REPUTA  AUG 2 7 REPUT	1 LE2-018876

Invoice

Page 2 of 2

Date Invoice # 7/31/2014 9839



105 W John St Seattle WA 98119 USA 888-285-4548 Fax 206.299.3380

	Charles Kindigh ediale (manenaren eta
	Markin Kirdilih kediala in samanangan kelalangan menangan kelalan di
	<b>建聚结果性基础在设施制度的基础</b>
The state of the s	AND THE PROPERTY OF THE PARTY O
	1 1
	i I
	• }
	. i
	1 1
	: I :
the same of the sa	

Thank you for your business.

If you are tax exempt, please fax your certificate to 206.299.3380 or email to info@vievu.com.

Subtotal Shipping Cost (UPS Ground) Tax (Sales Tax 7.5%) Total

les Tax 7.5%) 78.75 Total 1,151.75 Amount Due \$1,151.75

1.050.00

Thank you for your belief in our products. Please visit www.vievu.com for software and product documentation.

Customer

Oakland Police Department (CA)

Invoice # Amount Due Amount Paid

Signature:

9839 \$1,151.75

Please Enter Your Credit Card Information .

Type: \_\_\_\_Discover \_\_\_Master Card \_\_\_VISA \_\_\_American Express
Credit Card #: \_\_\_\_
Expiration Date: Month Year

VIEVU Remittance Slip

Make Checks Payable To

VIEVU 105 W John St Seattle WA 98119 USA

## Lim, Victor

From:

Lim, Victor

Sent:

Friday, June 27, 2014 9:06 AM

To:

support@vievu.com PDRD - Camera System

Cc: Subject:

RMA

Good morning,

Please provide a RMA for the following 7 PDRDs

PDRD#	video	Reason
LE2-004973	yes	Damaged usb
LE2-006043	no	No new video after recordings
LE2-013293	yes	Damaged usb
LE2-015872	no	damaged screw for clip
LE2-017261	yes	will not turn on
LE2-017688	yes	damaged lens cover
LE2-018566	yes	will not connect to server

RMA 104665

## Lim, Victor

From:

Josh Ellis <josh@vievu.com> on behalf of Support@vievu.com

Sent:

Wednesday, July 30, 2014 8:52 AM

To:

PDRD - Camera System

Subject:

VIEVU RMA 104665 - RESULTS

Hello Victor,

We have evaluated your camera(s) under RMA 104665. The results are as follows:

LE2-004973: Broken USB due to incorrect insertion of cable or other foreign object

LE2-006043: Camera defect repaired. Camera passed all tests. Camera will be returned

LE2-013293: Broken USB due to incorrect insertion of cable or other foreign object

LE2-015872: Clip or screw thread damage due to failure to loosen screw before clip rotation or blunt trauma

LE2-017261: Failure in case seal

LE2-017688: Lens cover broken due to blunt trauma

LE2-018566: Broken USB due to incorrect insertion of cable or other foreign object

We have determined that your camera(s) is(are) outside our warranty terms and that the repair costs will be \$1,050.00 plus shipping. Per our standing agreement this falls under the repair limit of \$2,500.00 so we are automatically processing the repair and submitting the repair fee to you for payment.

We appreciate your understanding that we cannot repair cameras for free that are not covered by a warranty. If you would like to review our warranty terms, please click here: <a href="http://www.vievu.com/termsandpolicies/">http://www.vievu.com/termsandpolicies/</a>

Best regards, VIEVU Customer Support