



Update Results



Address History with Inspection Log

CONTACT_TYPE = Applicant, Complainant, Neighbor, Occupant/Tenant, Tenant/Occupant
 CONTACT_TYPE Blank
 ADDR_PARTIAL Begins With 2324 ADELINE
 APN = (blank)
 DATE_OPENED >= 1/1/1980
 DATE_OPENED <= 12/31/2020

Record ID: [0902280](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: ALTERED ELECTRICAL SYSTEM, INTERIOR WALLS BUILT, SUMP PUMPS DISCHARGEIN UNAPPROVED AREA.

Date Opened: 4/22/2009

Record Status: Open

Record Status Date: 4/23/2009

Job Value: \$0.00

Requestor: RICHARD BOTTO

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
4/23/2009		1st Inspection	Violation Verified	VERIFIED
5/1/2009		1st Inspection	Violation Verified	VERIFIED
5/11/2009		1st Inspection	No Entry	IN PROGRESS
5/20/2009		1st Inspection	No Entry	IN PROCESS
6/19/2009		1st Inspection	Unable to Verify	Reinsp requested from insp result 82 on 05/20/09

Record ID: [ZC032564](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: General Manufacturing Activity: Machine Shop (metal work). Continuation of legal nonconforming use. M-20/S-16

Date Opened: 9/16/2003

Record Status: Approved

Record Status Date: 9/16/2003

Job Value: \$0.00

Requestor: RICHARD SMITH

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
-----------------	----------------	-----------------	-----------------	-----------------

Record ID: [0205252](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: CONSTRUCTION WITHOUT PERMITS, USING PCV PIPING

Date Opened: 6/18/2002

Record Status: Non-Actionable

Record Status Date:

Job Value: \$0.00

Requestor:

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
6/19/2002		1st Inspection	No Violations	

Record ID: [SL010416](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description:

Date Opened: 5/7/2001

Record Status: Final

Record Status Date: 5/11/2001

Job Value: \$0.00

Requestor: STREAMLINE INC.

:

Business Name:

License #: 672250

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
-----------------	----------------	-----------------	-----------------	-----------------

For real-time, direct access to information via the Internet, 24 hours a day - <https://aca.accela.com/oakland>



Update Results



Address History with Comments

CONTACT_TYPE = Applicant, Complainant, Neighbor, Occupant/Tenant, Tenant/Occupant
 CONTACT_TYPE Blank
 ADDR_PARTIAL Begins With 2324 ADELINE
 APN = (blank)
 DATE_OPENED >= 1/1/1980
 DATE_OPENED <= 12/31/2020

Record ID: [0902280](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: ALTERED ELECTRICAL SYSTEM, INTERIOR WALLS BUILT, SUMP PUMPS DISCHARGE IN UNAPPROVED AREA.

Date Opened: 4/22/2009

Record Status: Open

Record Status Date: 4/23/2009

Job Value: \$0.00

Requestor: RICHARD BOTTO

:

Business Name:

License #:

Comment Date	Commenter	Comment
--------------	-----------	---------

4/22/2009 12:00:00 AM	PTS	ALTERED ELECTRICAL SYSTEM, INTERIOR WALLS BUILT, SUMP PUMPS DISCHARGE IN UNAPPROVED AREA.
-----------------------	-----	---

1/21/2014 8:36:21 PM	PTS	Call tenant, RICHARD BOTTO, at 388-4503 for more information and / or for accessing the building. >>> 04/22/2009 13:36:15 DUNAW#C 0216 04/24/09 Ownership verified; per win2data and County Assessor Display. Original complaint; COMMERCIAL BUILDING - POOR WIRING AND BREAKER IS BAD CONDITION, WIRED IN THE WOODEN SHED, RAW SEWAGE LEAK IN THE TOILET. (TENANT COMPLAINT). Richard Botto complainant; Electrical issues include wiring without permits, substandard wiring. Building issues include wall and floor systems built without permits. Sump pumps that discharge onto the sidewalk.Richard and I didn't look at the bathroom due to time. Site needs field check. >>> 04/24/2009 11:34:02 WILMO#G 0160 Survey inspection needed not a field check. >>> 04/28/2009 16:27:02 WILMO#G 0116 Survey inspection on 06/01/09 at 11:00 >>> 04/28/2009 16:28:17 WILMO#G 0116
----------------------	-----	--

Record ID: [ZC032564](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: General Manufacturing Activity: Machine Shop (metal work). Continuation of legal nonconforming use. M-20/S-16

Date Opened: 9/16/2003

Record Status: Approved

Record Status Date: 9/16/2003

Job Value: \$0.00

Requestor: RICHARD SMITH

:

Business Name:

License #:

Comment Date	Commenter	Comment
--------------	-----------	---------

Record ID: [0205252](#)

Address: 2324 ADELINE ST

APN: 005 042700209

Unit #:

Description: CONSTRUCTION WITHOUT PERMITS, USING PCV PIPING

Date Opened: 6/18/2002

Record Status: Non-Actionable

Record Status Date:

Job Value: \$0.00

Requestor:

:

Business Name:**License #:**

Comment Date	Commenter	Comment
---------------------	------------------	----------------

6/18/2002 12:00:00 AM	PTS	CONSTRUCTION WITHOUT PERMITS, USING PCV PIPING
-----------------------	-----	--

1/21/2014 8:39:19 PM	PTS	6/18/02-per caller the water main cracked and some company came to the location last night with jack hammers and other equipment to do repai rs without permits on file as of 9:30am today.Caller stated they used the wrong material to patch the broken area/Nina >>> 06/18/2002 09:28:25 ELLIS#NL 0075
----------------------	-----	---

Record ID: [SL010416](#)**Address:** 2324 ADELINE ST**APN:** 005 042700209**Unit #:****Description:****Date Opened:** 5/7/2001**Record Status:** Final**Record Status Date:** 5/11/2001**Job Value:** \$0.00**Requestor:** STREAMLINE INC.

:

Business Name:**License #:** 672250

Comment Date	Commenter	Comment
---------------------	------------------	----------------

For real-time, direct access to information via the Internet, 24 hours a day - <https://aca.accela.com/oakland>