



Record Detail with Inspection Log

Record ID: 1600426

Description: ILLEGAL MARIJUANA GROWING OPERATION REFERRED BY CITY ATTORNEY'S OFFICE. POSSIBLE ILLEGAL ELECTRICAL, PLUMBING, MECHANICAL & PLUMBING.

APN: 048D727804400

Address: 2822 CHELSEA DR

Unit #:

Date Opened: 2/5/2016

Record Status: Pending Investigation

Record Status Date: 2/5/2016

Job Value: \$0.00

Requestor:

:

Business Name:

License #:

Inspection Date	Inspector Name	Inspection Type	Status / Result	Result Comments
2/5/2016	Travis Ha	1st Inspection	Violation Verified	2-5-2016 Violation verified. NOV Tc
2/10/2016	Travis Ha	Follow-up Inspection	Abated	2-10-16 Tenant made require repairs.



Record Detail with Comments

Record ID: 1600426

Description: ILLEGAL MARIJUNA GROWING OPERATION REFERRED BY CITY ATTORNEY'S OFFICE. POSSIBLE ILLEGAL ELECTRICAL, PLUMBING, MECHANICAL & PLUMBING.

APN: 048D727804400

Address: 2822 CHELSEA DR

Unit #:

Date Opened: 2/5/2016

Record Status: Pending Investigation

Record Status Date: 2/5/2016

Job Value: \$0.00

Requestor:

:

Business Name:

License #:

Comment Date	Commenter	Comment
2/8/2016 9:46:28 AM	THA	2-5-2016 Site visit with Gene Martinelli. Violation verified, exhaust vent missing cap, junction box lack cover, 1 outlet detach from wall, subpanel extra feed wire need to be remove.
2/16/2016 9:16:30 AM	THA	2-10-16 Tenant made require repairs, junction box cover, took out electrical wire form sub panel, cover up vent.