



Update Results



CITY OF OAKLAND

Address History with Inspection Log

CONTACT_TYPE = Complainant, Neighbor, Tenant/Occupant, Applicant, Lienee

CONTACT_TYPE = Blank

STREET_NBR = 2000

STREET_NAME : Begins With 36

STREET_TYPE : Begins With

APN = ----

DATE_OPENED >=

DATE_OPENED <= 12/31/2017

RECORD_TYPE_SUBTYPE <> Soft Story Retrofit Validation

RECORD_TYPE_TYPE <> Lien

Record ID: 0008695**Address: 2000 36TH AVE, #107****APN: 032 208402202****Unit #: 107****Description: KITCHEN FLOOR DETERIORATED; LIVING ROOM WINDOW AND WALL HEATER ARE INOPERABLE; MILDEW IN BATHROOM****Date Opened: 8/31/2000****Record Status: Abated****Record Status Date: 12/18/2000****Job Value: \$0.00****Requestor: MATTHEW FERNANEZ**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|-------------------------|---|-----------------------------------|---|
| 9/1/2000 | DAVID C MILES | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | |
| 9/7/2000 | DAVID C MILES | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | |
| 10/24/2000 | KIM NGUYEN | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | Scheduled reinsp from "65" result of insp 09/07/00 |
| 11/17/2000 | JOSEPH DELAGRANGE | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | TALK TO DM (FEE CHARGE) |
| 12/18/2000 | JOSEPH DELAGRANGE | 1st Inspection | Violation Verified | |
| 12/18/2000 | PERMIT TRACKING CODE | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Inspection voided | Inspection voided 06/19/01 - complaint abated 12/18/00 |

Record ID: 0105539**Address: 2000 36TH AVE, ##107****APN: 032 208402202****Unit #: #107****Description: WINDOWS UNSAFE****Date Opened: 6/27/2001****Record Status: No Violation Found**

Record Status Date:**Job Value: \$0.00****Requestor:**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|---|--------------------------|---|
| 6/28/2001 | | 1st Inspection | No Entry | Scheduled inspection voided by result code 97 on 08/10/01 |
| 8/10/2001 | | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint Not Applicable | |

Record ID: [0109557](#)**Address: 2000 36TH AVE, #214****APN: 032 208402202****Unit #: 214****Description: CEILING LEAKING @ BEDROOM. REPAIR ROOF AND EXISTING DAMAGE ON CEILINGAND FLOORING. TRASH @ REAR OF BUILDING. REMOVE AND MAINTAIN SANITARY.****Date Opened: 11/16/2001****Record Status: Abated****Record Status Date: 12/24/2001****Job Value: \$0.00****Requestor: MARIA RAMIREZ**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|---|--------------------------------|---|
| 11/19/2001 | JORGE REYES | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | MARIA 261-4513 |
| 12/24/2001 | JORGE REYES | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint ABated | Auto scheduled from 62 result on 11/19/01 |

Record ID: [0110154](#)**Address: 2000 36TH AVE, #214****APN: 032 208402202****Unit #: 214****Description: CEILING IS LEAKING FOR > A MONTH RUINING CARPET AND BED****Date Opened: 12/14/2001****Record Status: Abated****Record Status Date: 12/17/2001****Job Value: \$0.00****Requestor: MARIA RAMIREZ**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|---|------------------|------------------------|
| 12/17/2001 | JORGE REYES | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint ABated | MARIA RAMIREZ 261-4513 |

Record ID: [0400199](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: GARBAGE IS PILED HIGH CONSISTENTLY BY TENANTS, FURNITURE, TREES, ETC.&PUTTING EXCESS GARBAGE INTO BINS NEXT DOOR.****Date Opened: 1/14/2004****Record Status: Abated****Record Status Date: 2/23/2004****Job Value: \$0.00****Requestor:**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

1/16/2004

OMC - BLIGHT ABATEMENT
OMC-Injurious OMC-1Viol. verified / not
corrected

2/23/2004

WING LOO

OMC - BLIGHT ABATEMENT
OMC-Injurious OMC-1

Complaint ABated

Auto scheduled from 62 result on
01/16/04**Record ID: 0400408****Address: 2000 36TH AVE, ##213****APN: 032 208402202****Unit #: #213****Description: NO HEAT, AND WINDOWS DON'T WORK****Date Opened: 1/29/2004****Record Status: Abated****Record Status Date: 5/5/2004****Job Value: \$0.00****Requestor:**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|--------------------|--|
| 1/30/2004 | KEN PALMER | 1st Inspection | Violation Verified | |
| 3/5/2004 | KEN PALMER | 1st Inspection | Violation Verified | Reinsp requested from insp result 93 on 01/30/04 |
| 3/16/2004 | KEN PALMER | 1st Inspection | No Violations | PROGRESS |
| 3/24/2004 | KEN PALMER | 1st Inspection | No Violations | Reinsp generated from insp result 95 on 03/16/04 |
| 4/1/2004 | KEN PALMER | 1st Inspection | No Violations | Reinsp generated from insp result 95 on 03/24/04 |
| 4/9/2004 | KEN PALMER | 1st Inspection | No Violations | Reinsp generated from insp result 95 on 04/01/04 |
| 5/5/2004 | KEN PALMER | 1st Inspection | Violation Verified | Reinsp requested from insp result 95 on 04/09/04 |

Record ID: 0708470**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: DILAPIDATED STAIRS/CONCRETE IS BROKEN****Date Opened: 11/16/2007****Record Status: Abated****Record Status Date: 12/17/2007****Job Value: \$0.00****Requestor: OAKLAND FIRE**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|-------------------|---|--------------------|-----------------|
| 11/19/2007 | EUGENE MARTINELLI | 1st Inspection | Violation Verified | NOTICE TO ABATE |
| 12/17/2007 | EUGENE MARTINELLI | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint ABated | ABATED |

Record ID: 0901397**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: WATER DAMAGE****Date Opened: 3/18/2009****Record Status: No Violation Found****Record Status Date:****Job Value: \$0.00****Requestor:**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|-----------------|---|--------------------------|-----------------|
| 3/19/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint Not Applicable | NON ACTIONABLE |

Record ID: [0902304](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:****Description:** OVERGROWN VEGETATION, GRAFFITI**Date Opened:** 4/23/2009**Record Status:** Abated**Record Status Date:** 6/15/2009**Job Value:** \$0.00**Requestor:** JABER JAD & SUAD TRS ETAL

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|-----------------|---|--------------------------------|--|
| 4/24/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | VERIFIED |
| 5/5/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | NO PROGRESS; NTA BL. |
| 5/18/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | PROGRESS; NTA BL. SUBMITTED |
| 6/2/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | NO PROGRESS CLEAN UP SUBMITTED |
| 6/12/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | GRAFFITI REMOVED; MORE PROGRESS REQUIRED |
| 6/15/2009 | ROBERT WALKER | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | SITE CLEAN |
| 6/15/2009 | ROBERT N BERNAL | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint ABated | |
| 6/29/2009 | ROBERT N BERNAL | 1st Inspection | No Entry | Scheduled inspection voided by result code 98 on 06/15/09 |

Record ID: [0903127](#)**Address:** 2000 36TH AVE, #105**APN:** 032 208402202**Unit #:** 105**Description:** STOVE TOP DEFECTIVE, MOLD IN THE BATHROOM MAKING CHILDREN SICK, ROACHES, WORN OUT CARPET, TOILET CRACKED AND LEAKING ETC.**Date Opened:** 5/27/2009**Record Status:** Abated**Record Status Date:** 7/29/2009**Job Value:** \$0.00**Requestor:** IRMA BARRAZA

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|---|--------------------------------|-----------------|
| 5/28/2009 | GREGORY CLARKE | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | NTA SUBMITTED |
| 6/29/2009 | GREGORY CLARKE | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Substantial compliance/no fees | PROGRESS |
| 7/29/2009 | GREGORY CLARKE | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Complaint ABated | ABATED |

Record ID: [1102523](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:****Description:** TOUGH ON BANKS**Date Opened:** 4/9/2011**Record Status:** Violation Verified

Record Status Date: 4/26/2011**Job Value: \$0.00****Requestor:****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|---|--------------------------------|--|
| 4/26/2011 | KIM NGUYEN | OMC - BLIGHT ABATEMENT OMC-Injurious OMC-1 | Viol. verified / not corrected | OVERGROWTH |
| 5/26/2011 | KIM NGUYEN | 1st Inspection | Unable to Verify | Reinsp requested from insp result 93 on 04/26/11 |

Record ID: [1402386](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: TRASH & DEBRIS ALL AROUND COMPLEX EXTERIOR****Date Opened: 6/20/2014****Record Status: Abated****Record Status Date: 8/5/2014****Job Value:****Requestor:****: AARON LAI****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|---|
| 6/24/2014 | | 1st Inspection | Violation Verified | |
| 8/5/2014 | Randy Schimm | Follow-up Inspection | Abated | 08/05/2014 : RSchimm - Onsite inspection, photos taken, abated. |
| | Dennis Foster | 1st Inspection | Scheduled | |

Record ID: [1402387](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: UNIT 201; MILDEW ON WALLS IN BEDROOM, WINDOW DETERIORATED, TOILET & BATHROOM HAVE LEAKS, CABINETS ROTTED, LEAK IN GARAGE.****Date Opened: 6/20/2014****Record Status: Abated****Record Status Date: 8/19/2014****Job Value:****Requestor:****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|---|
| 6/24/2014 | Randy Schimm | 1st Inspection | Violation Verified | |
| 8/5/2014 | Randy Schimm | Follow-up Inspection | Partially Abated | |
| 8/19/2014 | Randy Schimm | Follow-up Inspection | Abated | 08/19/2014 : RSchimm - Onsite inspection, photos taken, Abated. |
| | Dennis Foster | 1st Inspection | Scheduled | |

Record ID: [1502536](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: Unit #118 - No working heater.****Date Opened: 7/21/2015****Record Status: Non-Actionable****Record Status Date: 8/12/2015****Job Value: \$0.00****Requestor:****: Altagracia Mendoza**

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 8/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| | | Follow-up Inspection | Scheduled | |

Record ID: [1502537](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:**

Description: Unit #115 - Leaking sink, stove vent not working, chipping paint in bathroom wall & ceiling.

Date Opened: 7/21/2015**Record Status:** Abated**Record Status Date:** 10/22/2015**Job Value:** \$0.00**Requestor:****: Sonia Pina****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 8/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 9/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | Abated | |

Record ID: [1502538](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:**

Description: Unit #123 - No working heater, leaking sink, and exposed ceiling.

Date Opened: 7/21/2015**Record Status:** Closed**Record Status Date:** 2/1/2016**Job Value:** \$0.00**Requestor:****: Jose Cruz****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 8/14/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 8/14/2015 | Hugo Barron | Follow-up Inspection | Abated | |
| 9/15/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 1/21/2016 | Hugo Barron | Follow-up Inspection | No Entry | |

Record ID: [1502539](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:**

Description: Unit #107 - Broken window in bathroom, leaking sink, and damaged faucet.

Date Opened: 7/21/2015**Record Status:** Closed**Record Status Date:** 2/1/2016**Job Value:** \$0.00**Requestor:****: Rosa Montoya****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 8/10/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 9/10/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | Abated | |

1/21/2016 Hugo Barron Follow-up Inspection No Entry

Record ID: 1502540

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #116 - Damaged carpet, tripping hazard.

Date Opened: 7/21/2015

Record Status: Closed

Record Status Date: 4/6/2016

Job Value: \$0.00

Requestor:

: Belem Resendiz

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 8/10/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 9/10/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 1/21/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| 4/5/2016 | Hugo Barron | Follow-up Inspection | Abated | |
| | | Follow-up Inspection | Pending | |

Record ID: 1502541

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #109 - Bathroom ceiling leaking which is falling and crumbling.

Date Opened: 7/21/2015

Record Status: Abated

Record Status Date: 10/22/2015

Job Value: \$0.00

Requestor:

: Salvador Diaz

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------------|--------------------|-----------------|
| 8/10/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 9/10/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | Abated | |
| | Hugo Barron | Monitoring Inspection | Cancelled | |

Record ID: 1502543

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #126 - Toilet is loose and leaking and flooded carpet.

Date Opened: 7/21/2015

Record Status: Closed

Record Status Date: 1/22/2016

Job Value: \$0.00

Requestor:

: Carmen Rosales

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 1/21/2016 | Hugo Barron | Follow-up Inspection | No Entry | |

Record ID: 1502544

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #117 - Bathroom ceiling is crumbling and mold on wall.

Date Opened: 7/21/2015

Record Status: Abated

Record Status Date: 1/22/2016

Job Value: \$0.00

Requestor:

: Jose Rojas

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 8/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 9/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 1/21/2016 | Hugo Barron | Follow-up Inspection | Abated | |

Record ID: [1502545](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #127 - Water leaking from ceiling, broken faucet, poor drainage, and broken kitchen vent.

Date Opened: 7/21/2015

Record Status: Closed

Record Status Date: 10/30/2015

Job Value: \$0.00

Requestor:

: Olegaria Ochoa

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|------------------|-----------------|
| 10/30/2015 | Hugo Barron | 1st Inspection | Unable to Verify | |

Record ID: [1502546](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #201 - Exposed wall wiring, broken floor in kitchen, and chipping paint.

Date Opened: 7/21/2015

Record Status: Closed

Record Status Date: 10/30/2015

Job Value: \$0.00

Requestor:

: Magda Delcid

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 10/30/2015 | Hugo Barron | Follow-up Inspection | Abated | |

Record ID: [1502548](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Unit #217 - Holes in wall, exposed wall wiring, leaking toilet, broken closet doors, and leaking refrigerator that caused mold in kitchen.

Date Opened: 7/21/2015

Record Status: Abated

Record Status Date: 11/30/2015

Job Value: \$0.00

Requestor:

: Maria Mendoza

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-----------------|-----------------|
| 8/13/2015 | Hugo Barron | Follow-up Inspection | No Abated | |

| | | | |
|------------|-------------|----------------------|-----------|
| 9/14/2015 | Hugo Barron | Follow-up Inspection | No Abated |
| 10/28/2015 | Hugo Barron | Follow-up Inspection | No Entry |
| 11/30/2015 | Hugo Barron | Follow-up Inspection | Abated |
| | | Follow-up Inspection | Scheduled |

Record ID: [1502556](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Unit #215 - Falling doors, non-working light fixtures, and broken closet doors.

Date Opened: 7/21/2015**Record Status: Violation Verified****Record Status Date: 8/13/2015****Job Value: \$0.00****Requestor:****: Ernesto Cardenas****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|------------------------|-----------------------|------------------------|------------------------|------------------------|
| 8/13/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 9/14/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/28/2015 | Hugo Barron | Follow-up Inspection | Partially Abated | |
| 11/30/2015 | Hugo Barron | Follow-up Inspection | No Entry | |

Record ID: [1502557](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Unit #205 - Moist on wall causing mold and mildew.

Date Opened: 7/21/2015**Record Status: Abated****Record Status Date: 8/14/2015****Job Value: \$0.00****Requestor:****: Jesus Mejia****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|------------------------|-----------------------|------------------------|------------------------|------------------------|
| 8/13/2015 | Hugo Barron | Follow-up Inspection | Abated | |

Record ID: [1502558](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Unit #207 - Chipping paint and mold.

Date Opened: 7/21/2015**Record Status: Closed****Record Status Date: 10/30/2015****Job Value: \$0.00****Requestor:****: Johana Ordonez****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|------------------------|-----------------------|------------------------|------------------------|------------------------|
| 10/30/2015 | Hugo Barron | Follow-up Inspection | Abated | |

Record ID: [1502559](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Unit #219 - Leaking in kitchen and bathroom, flooring is peeling up, tripping hazard.

Date Opened: 7/21/2015

Record Status: Violation Verified**Record Status Date: 8/11/2015****Job Value: \$0.00****Requestor:****: Marta Munoz****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|------------------|-----------------|
| 8/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 9/11/2015 | Hugo Barron | Follow-up Inspection | No Abated | |
| 10/28/2015 | Hugo Barron | Follow-up Inspection | Partially Abated | |
| 11/30/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 3/23/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| 4/22/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| 5/13/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| 6/2/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| | | Follow-up Inspection | Pending | |
| | | Follow-up Inspection | Pending | |

Record ID: [1503239](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Apt. 105: Hole in ceiling-bathroom. Window corners rotting-bedroom and living room. Unsecure main entrance door-not sealed/closing properly. Stove ventilation broken.

Date Opened: 9/14/2015**Record Status: Closed****Record Status Date: 2/1/2016****Job Value: \$0.00****Requestor:****: Blanca****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 9/16/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 10/16/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 10/21/2015 | Hugo Barron | Follow-up Inspection | No Entry | |
| 1/21/2016 | Hugo Barron | Follow-up Inspection | No Entry | |

Record ID: [1503479](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: Severely overflowing trash cans on property with bags of trash and debris all over yard that's attracting rats on property.

Date Opened: 9/29/2015**Record Status: Notice of Violation Sent****Record Status Date: 10/5/2015****Job Value: \$0.00****Requestor:****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 10/1/2015 | Hugo Barron | 1st Inspection | Violation Verified | |
| 11/2/2015 | Hugo Barron | Follow-up Inspection | No Abated | |

Record ID: [1602629](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: UNIT 209: windows screens missing, no smoke detectors, some light and receptacles are malfunctioning

Date Opened: 7/13/2016

Record Status: Violation Verified**Record Status Date: 7/21/2016****Job Value: \$0.00****Requestor:****: GLADYS****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|--------------------|-----------------|
| 7/19/2016 | Hugo Barron | 1st Inspection | Violation Verified | |
| 9/14/2016 | Hugo Barron | Follow-up Inspection | No Entry | |
| 10/17/2016 | Hugo Barron | Follow-up Inspection | No Abated | |
| 12/6/2016 | Hugo Barron | Follow-up Inspection | No Entry | |
| 12/7/2016 | Hugo Barron | Follow-up Inspection | No Abated | |

Record ID: [9401014](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: HS42467:9401014 ROTTEN WOOD IN FLOOR, WATER RUNS FROM RESTROOM TO DOOR; SMALL CHILDREN.****Date Opened: 10/11/1994****Record Status: Closed****Record Status Date: 11/22/1994****Job Value: \$0.00****Requestor: JOHN PAGE FROM ENVIRONMENTAL HEALTH DEPT.****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9401015](#)**Address: 2000 36TH AVE, #105****APN: 032 208402202****Unit #: 105****Description: B42505****Date Opened: 10/12/1994****Record Status: Closed****Record Status Date: 7/19/1999****Job Value: \$0.00****Requestor:****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9401016](#)**Address: 2000 36TH AVE, #105****APN: 032 208402202****Unit #: 105****Description: HS42376****Date Opened: 10/5/1994****Record Status: Closed****Record Status Date: 7/19/1999****Job Value: \$0.00****Requestor:****:****Business Name:****License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9403637](#)**Address: 2000 36TH AVE**

APN: 032 208402202**Unit #:****Description:** GARBAGE IS IN REAR OF PROPERTY, OVERFLOWING INTO THE CREEK, FENCE ISBROKEN.**Date Opened:** 12/22/1994**Record Status:** Closed**Record Status Date:** 11/17/2000**Job Value:** \$0.00**Requestor:**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9500400](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:****Description:** B43324-HEATER-SECURE TOILET**Date Opened:** 11/21/1994**Record Status:** Closed**Record Status Date:** 1/4/1995**Job Value:** \$0.00**Requestor:** AVA RIGHTS

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9503619](#)**Address:** 2000 36TH AVE**APN:** 032 208402202**Unit #:****Description:** GARBAGE OVERFLOWING INTO CREEK, GRAFFITI, AUTO PARTS**Date Opened:** 6/9/1995**Record Status:** Closed**Record Status Date:** 7/12/1995**Job Value:** \$0.00**Requestor:** OPD - BEAT HEALTH

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9505089](#)**Address:** 2000 36TH AVE, #106**APN:** 032 208402202**Unit #:** 106**Description:** { NOT VACANT } TUB CONTINUOUSLY LEAKS, ROACHES, PIPES BUSTED.**Date Opened:** 8/23/1995**Record Status:** Abated**Record Status Date:** 9/15/1995**Job Value:** \$0.00**Requestor:** (T) MARLON BLACK

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9505093](#)**Address:** 2000 36TH AVE, #102**APN:** 032 208402202**Unit #:** 102

Description: { NOT VACANT } WINDOWS ARE BROKE OUT, DOORS ARE BROKEN , PLUMBINGPLUMBING PROBLEMS, ROACHES.

Date Opened: 8/23/1995

Record Status: Closed

Record Status Date: 9/6/1995

Job Value: \$0.00

Requestor: (T) TONI MARZETTE

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9505100](#)

Address: 2000 36TH AVE, #201

APN: 032 208402202

Unit #: 201

Description: {NOT VACANT} SEWER SMELL IN THE BATHROOM , PIPES BUSTED

Date Opened: 8/23/1995

Record Status: Closed

Record Status Date: 9/12/1995

Job Value: \$0.00

Requestor: (T) REDELA

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9505138](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: GARBAGE IN NOT BEING EMPTIED,SECURITY SYSTEM NOT WORKING,WIRES HANG-ING DOWN/DRUG DEALERS/NEEDLES ON THE GROUND/CHILD GOT HEPITITAS

Date Opened: 8/25/1995

Record Status: Abated

Record Status Date: 7/14/1995

Job Value: \$0.00

Requestor: BARBATRA WILSON

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9601920](#)

Address: 2000 36TH AVE, ##214

APN: 032 208402202

Unit #: #214

Description: BUZZARD DOESNT WORK PEOPLE HAVE TO CALL BEFORE THEY COME. DANGEROUSHAZARD. SINK LEAKING, BATHROOM SINK STOPPED UP, SWIMMING POOL DIRTY.

Date Opened: 4/18/1996

Record Status: Closed

Record Status Date: 8/30/1996

Job Value: \$0.00

Requestor: DARNELL OLIVER

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9604061](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: GARBAGE AND DEBRIS IN THE PARKING LOT, TUB IN BATH IS PLUGGED, CLOSETDORS ARE OFF TRACK (DRUG TRAFFIC)

Date Opened: 7/23/1996

Record Status: Closed
 Record Status Date: 7/16/1999
 Job Value: \$0.00
 Requestor: TENANT TIFFANY TUCKER

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9606587](#)

Address: 2000 36TH AVE, #101

APN: 032 208402202

Unit #: 101

Description: HEATER IS LEAKING GAS; PG&E SAID IT IS A HEALTH HAZARD.

Date Opened: 12/3/1996

Record Status: Closed

Record Status Date: 1/16/1997

Job Value: \$0.00

Requestor: CHRISTINA

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9606613](#)

Address: 2000 36TH AVE, #222

APN: 032 208402202

Unit #: 222

Description: BROKEN WATER PIPES IN BUILDING, TOILET BROKEN, KITCHEN SINK, KITCHENTITLE COMING UP, BROKEN WINDOW IN BATHROOM AND NO HOT WATER.

Date Opened: 12/4/1996

Record Status: Closed

Record Status Date: 2/5/1997

Job Value: \$0.00

Requestor: BRANDY BOSTIC

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9606831](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: WINDOWS BROKEN OUT, BOARDED UP

Date Opened: 12/16/1996

Record Status: Closed

Record Status Date: 12/26/1996

Job Value: \$0.00

Requestor: TIFFANY ROSS

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9702387](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: MOLD - FUNGUS - MUSHROOM ON THE WALL, CEILING PEELING AND WATER LEAKS

Date Opened: 5/5/1997

Record Status: Closed

Record Status Date: 6/6/1997

Job Value: \$0.00
 Requestor: MARIA TAVOR/NO ENGLISH
 :
 Business Name:
 License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9703104](#)

Address: 2000 36TH #113 AVE

APN: 006 003506000

Unit #:

Description: CREATED 05/29/97 FROM DBASE #2784, TYPE=B

Date Opened: 1/10/1994

Record Status: Open

Record Status Date:

Job Value: \$0.00

Requestor:

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9800046](#)

Address: 2000 36TH AVE, ##114

APN: 032 208402202

Unit #: #114

Description: NO HOT WATER

Date Opened: 1/6/1998

Record Status: Closed

Record Status Date: 6/15/1998

Job Value: \$0.00

Requestor: BERNADINE SATANA

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9800175](#)

Address: 2000 36TH AVE, #224

APN: 032 208402202

Unit #: 224

Description: WATER LEAKS THROUGH WINDOWS, MILDEW GROWING AROUND WINDOW SILL, NO HOTWATER IN THE EVENING, CARPET NEEDS REPLACEMENT, ROACHES, MICE, KITCHEN

Date Opened: 1/13/1998

Record Status: Closed

Record Status Date: 3/3/1998

Job Value: \$0.00

Requestor: (T) SHAWNA HORTA

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [9800177](#)

Address: 2000 36TH AVE, #210

APN: 032 208402202

Unit #: 210

Description: NO HOT WATER IN THE EVENING, KITCHEN SINK & BATHROOM TOILET CLOGS UP, INFESTED WITH ROACHES, HANDRAILS ON 2ND FLOOR WEAK

Date Opened: 1/13/1998

Record Status: Open

Record Status Date:

Job Value: \$0.00

Requestor: (T) KATRINA HILL

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: 9800178**Address: 2000 36TH AVE, #210****APN: 032 208402202****Unit #: 210****Description: NO HOT WATER IN THE EVENING, KITCHEN SINK & BATHROOM TOILETS CLOG UP, ROACHES, HANDRAILS ON 2ND FLOOR ARE MISSING BARS.****Date Opened: 1/13/1998****Record Status: Closed****Record Status Date: 11/17/2000****Job Value: \$0.00****Requestor: (T) KATRINA HILL**

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: 9800179**Address: 2000 36TH AVE, #220****APN: 032 208402202****Unit #: 220****Description: BATH TUB AND SINK DRAINS ARE CLOGGED, WINDOW LACKING INSULATION ROACH AND RAT INFESTATION, NO HEAT, WINDOW PANE MISSING, FLOORS ARE ROTTED****Date Opened: 1/13/1998****Record Status: Closed****Record Status Date: 2/6/1998****Job Value: \$0.00****Requestor: T/ANABELL SANTIGO**

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: 9801004**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:****Description: RAW SEWAGE COMING UP THROUGH BATH SINK****Date Opened: 2/23/1998****Record Status: Closed****Record Status Date: 3/2/1998****Job Value: \$0.00****Requestor: T/KATRINA HILL**

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: 9809467**Address: 2000 36TH AVE, #119****APN: 032 208402202****Unit #: 119****Description: SEWAGE IS LEAKING THRU CEILING, TOILET DON'T WORK, RAW SEWAGE BACKS UP IN SINK, FLOOR IS COMING UP****Date Opened: 12/18/1998****Record Status: Open****Record Status Date:****Job Value: \$0.00****Requestor: T/ HERBERT & GLENDA WILLIAMS**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|------------------|------------------|
| 12/21/1998 | | 1st Inspection | Unable to Verify | HERBERT 261-1159 |

Record ID: [B1700782](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: PROW : Install new 1 wireless telecommunication antenna and new wood pole at existing wood utility pole location in public right of way. PLN16338

Date Opened: 2/23/2017**Record Status: On Hold****Record Status Date: 3/15/2017****Job Value: \$8,000.00****Requestor: Catherine Mendoza (Black & Veatch)**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [B8903714](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: REPLACE A COUPLE STUDS & SHEETROCK

Date Opened: 8/16/1989**Record Status: Expired****Record Status Date: 11/18/1991****Job Value: \$4,000.00****Requestor: DOUG SEILER**

:

Business Name:**License #:**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

12/1/1989

WALLBRD/SHINGLE 03N

APPROVED

12/6/1989

WALLBRD/SHINGLE 03N

APPROVED

Record ID: [B9005883](#)**Address: 2000 36TH AVE****APN: 032 208402202****Unit #:**

Description: REPAIR EXTERIOR WALL WHERE AUTO DAMAGED

Date Opened: 11/9/1990**Record Status: Final****Record Status Date: 12/19/1990****Job Value: \$800.00****Requestor: KNOLL PAUL BLDG & DEV CO INC**

:

Business Name:**License #: 475877**

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

11/19/1990

Frame

No Status

12/5/1990

ROUGH 03P

APPROVED

12/11/1990

WALLBRD/SHINGLE 03N

APPROVED

12/19/1990

FINAL BUILDING 04P

APPROVED

Record ID: [E8903110](#)**Address: 2000 36TH AVE, ##215****APN: 032 208402202****Unit #: #215**

Description: MOVE 1 PLUG

Date Opened: 9/20/1989

Record Status: Final
 Record Status Date: 2/13/1990
 Job Value: \$0.00
 Requestor: DOUG SEILER

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|----------------------|-------------------|-----------------|
| 9/28/1989 | | ROUGH 03P | CORRECTION NOTICE | |
| 2/13/1990 | | FINAL ELECTRICAL 04P | APPROVED | |

Record ID: [**M1101394**](#)

Address: 2000 36TH AVE, #211

APN: 032 208402202

Unit #: 211

Description: REPLACE WALL HEATER.

Date Opened: 8/30/2011

Record Status: Expired

Record Status Date: 3/16/2012

Job Value: \$0.00

Requestor: COPELAND MECHANICAL

:

Business Name:

License #: 622303

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [**PLN16338**](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Major Design Review near 2000 36th Avenue (new macro telecom on JPA pole in public right-of-way)

Date Opened: 11/4/2016

Record Status: Approved

Record Status Date: 2/15/2017

Job Value: \$0.00

Requestor:

:

Business Name: BLACK & VEATCH (A GOMEZ)

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [**RR1600002**](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: 1 COPY OF EACH COMPLAINT THAT IS HIGHLIGHTED

Date Opened: 1/28/2016

Record Status: Completed - Fees Due

Record Status Date: 2/8/2016

Job Value: \$0.00

Requestor:

: SHIRA LEVINE

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [**SS111330**](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: LEVEL 2 SCREENING REQUIRED

Date Opened: 9/30/2011

Record Status: Expired

Record Status Date: 4/1/2012

Job Value: \$0.00

Requestor: NICK SHIHADDEH

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC011249](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: HOME OCCUPATION FOR ARTISTIC AND CULTURAL PROMOTION

Date Opened: 6/21/2001

Record Status: Approved

Record Status Date: 6/21/2001

Job Value: \$0.00

Requestor: MANUEL SERRANO PATLAN

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC021433](#)

Address: 2000 36TH AVE, #219

APN: 032 208402202

Unit #: 219

Description: home office use for cleaning business - no clients, employees, or hazardous materials to have access to this site; no commercial traffic to have access to this site.

Date Opened: 5/29/2002

Record Status: Approved

Record Status Date: 5/29/2002

Job Value: \$0.00

Requestor: MARICELA ONTIVEROS

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC022320](#)

Address: 2000 36TH AVE, #201

APN: 032 208402202

Unit #: 201

Description: HOME OCCUPATION FOR CLEANING BUSINESS

Date Opened: 8/22/2002

Record Status: Approved

Record Status Date: 8/22/2002

Job Value: \$0.00

Requestor: IRMA LOPEZ

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC040898](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: Zoning Clearance for business license for home occupation (home office for janitorial business - cleaning at off-site locations)

Date Opened: 3/24/2004

Record Status: Approved

Record Status Date: 3/24/2004

Job Value: \$0.00
 Requestor: JUAN GUERRERO MEDINA
 :
 Business Name:
 License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC050976](#)

Address: 2000 36TH AVE, ##111

APN: 032 208402202

Unit #: #111

Description: Home office for computer service business.

Date Opened: 3/25/2005

Record Status: Approved

Record Status Date: 3/25/2005

Job Value: \$0.00

Requestor: PERRY LEE DALE

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC080207](#)

Address: 2000 36TH AVE

APN: 032 208402202

Unit #:

Description: ZONING CLEARANCE/HOME OCCUPATION--janitorial/cleaning business (see 3 prior ZC's for same use at this site), new owner; no stock in trade, no client traffic, no employees

Date Opened: 1/25/2008

Record Status: Approved

Record Status Date: 1/25/2008

Job Value: \$0.00

Requestor: RAUL HERNANDEZ

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC091956](#)

Address: 2000 36TH AVE, #209

APN: 032 208402202

Unit #: 209

Description: Home Occupation for a handyman business.

Date Opened: 9/24/2009

Record Status: Approved

Record Status Date: 9/24/2009

Job Value: \$0.00

Requestor: CARLOS PEREZ JACINTO

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: [ZC102147](#)

Address: 2000 36TH AVE, #125

APN: 032 208402202

Unit #: 125

Description: Home office for cleaning services business

Date Opened: 9/21/2010

Record Status: Approved

Record Status Date: 9/21/2010

Job Value: \$0.00

Requestor: MIRIAM CLAROS ZEPEDA

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

Record ID: ZC132534**Address: 2000 36TH AVE, #213****APN: 032 208402202****Unit #: 213****Description: Zoning clearance for a home occupation serving a flooring contractor business. All services done off-site. No storage. Home office only****Date Opened: 11/26/2013****Record Status: Approved****Record Status Date: 11/26/2013****Job Value: \$0.00****Requestor: JAIME ROMAN**

:

Business Name:

License #:

| Inspection Date | Inspector Name | Inspection Type | Status / Result | Result Comments |
|-----------------|----------------|-----------------|-----------------|-----------------|
|-----------------|----------------|-----------------|-----------------|-----------------|

For real-time, direct access to
information via the Internet, 24 hours a
day - <https://aca.accela.com/oakland>